

Refusal of MOT test certificate



Driver & Vehicle
Standards
Agency

(1) Vehicle identification number

1B7GG36N12S678410

(2a) Registration number (2b) Country of registration

BQ91YHQ

GB

Make and model

Plaxton Tourismo

(5) Vehicle category

M1

(4) Odometer

12,312 kilometres

(7) **Fail**

(6) **Do not drive until repaired (dangerous defects)**



- 54.1.a.ii Power steering: not working correctly and obviously affects steering control. Inner Offside. Axles: 7. Asdasd

(6) **Repair as soon as possible (minor defects)**

- 54.1.d.i Power steering: reservoir is below minimum level. Outer Nearside. Axles: 7.

Monitor and repair if necessary (advisories)

- 5.1 Compression Ignition Engines Statutory Smoke Meter Test:.. Dasdasdccc

(3b) Date of the test

26.02.2019

(3a) Location of the test

09-4129632, Abshire-Kub

(9) Testing organisation and inspector

**DRIVER AND VEHICLE STANDARDS AGENCY
CVS Dev1**

Test number

LEET1338

For a retest, you must get the defects fixed and arrange to take the vehicle to an authorized testing facility within 14 working days of the date of this test, and pay the appropriate payment.

NOT VALID

Check that this document is genuine by visiting **www.gov.uk/check-mot-history**

If any of the details are not correct, please contact DVSA by email at **enquiries@dvsa.gov.uk** or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at **www.gov.uk/mot-reminder** or by telephone on 0300 1239000.