

100

101

102

103

104

105

106

107

108

109

110

111

F26_001



Phone.

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

Company / customer
Project description
Drawing number
Commission

Manufacturer (company)

Path

Project name

Khoshkon-TOPS

Make

Type

Place of installation


Responsible for project


Part feature


Created on 9/1/2015

Edit date 2/22/2018 by (short name) Electronic


Number of pages 8

Modification	Date	Name	Khoshkon-TOPS		Modification				
					Electronic	Drawing number	Edited by	Page 1 Pg 8	




Modification	Date	Name	Rizesh	Modification	3/17/2018 Electronic				
SAM electronic	1396/9/30	Khoshkon-TOPS				Drawing number	Edited by M.Taghipoor	Page Pg	






Modification	Date	Name	Khoshkon-TOPS	Rizesh +	Modification	3/17/2018 Electronic			
							Drawing number	Edited by	Page Pg
									2 8







PARAMETER DRIVE00

PARAMETER DRIVE01

PARAMETER DRIVE02

PARAMETER DRIVE03

PARAMETER DRIVE04

PARAMETER DRIVE05

PARAMETER DRIVE06

PARAMETER DRIVE07

PARAMETER DRIVE08

PARAMETER DRIVE09

PARAMETER DRIVE10

PARAMETER DRIVE11

PARAMETER DRIVE12

PARAMETER DRIVE13

PARAMETER DRIVE14

PARAMETER DRIVE15

PARAMETER DRIVE16

PARAMETER DRIVE17

PARAMETER DRIVE18

PARAMETER DRIVE19

PARAMETER DRIVE20

PARAMETER DRIVE21

PARAMETER DRIVE22

PARAMETER DRIVE23

PARAMETER DRIVE24

PARAMETER DRIVE25

PARAMETER DRIVE26

PARAMETER DRIVE27

PARAMETER DRIVE28

PARAMETER DRIVE29

Parameters

Rizesh

Bardasht

PRESS

KATS

KAKE

GARRI

P0.04=1
P0.05=50
P0.06=1
P0.08=6
P0.09=2

P0.04=1
P0.05=50
P0.06=1
P0.08=6
P0.09=2

P0.04=1
P0.05=50
P0.06=1
P0.08=1
P0.09=0.5

P9.00=0
P9.01=4
P9.02=1500
P9.03=0.75
P9.04=1.5
P9.05=1

P9.00=0
P9.01=4
P9.02=1500
P9.03=0.75
P9.04=1.5
P9.05=1

P9.00=0
P9.01=4
P9.02=1500
P9.03=0.75
P9.04=1.5
P9.05=1

P9.16=0
P9.17=10
P9.18=0.5
PA.04=1
PA.05=100
PA.06=101
PA.13=010

P9.16=0
P9.17=10
P9.18=0.5
PA.04=1
PA.05=100
PA.06=101
PA.13=010

P9.16=0
P9.17=10
P9.18=0.5
PA.04=1
PA.05=100
PA.06=101
PA.13=010

KATS

TRAVERS

GARRI

P0.04=1
P0.05=50
P0.06=1
P0.08=6
P0.09=2

P0.04=1
P0.05=50
P0.06=1
P0.08=0
P0.09=1

P0.04=1
P0.05=50
P0.06=1
P0.08=1
P0.09=0.5

P9.00=0
P9.01=4
P9.02=1500
P9.03=0.75
P9.04=1.5
P9.05=1

P9.00=0
P9.01=4
P9.02=1500
P9.03=0.75
P9.04=1.5
P9.05=1

P9.00=0
P9.01=4
P9.02=1500
P9.03=0.75
P9.04=1.5
P9.05=1

P9.16=0
P9.17=10
P9.18=0.5
PA.04=1
PA.05=100
PA.06=101
PA.13=010

P9.16=0
P9.17=10
P9.18=0.5
PA.04=1
PA.05=100
PA.06=101
PA.13=010

P9.16=0
P9.17=10
P9.18=0.5
PA.04=1
PA.05=100
PA.06=101
PA.13=010

KATS

TRAVERS

P0.04=1
P0.05=50
P0.06=1
P0.08=6
P0.09=2

P0.04=1
P0.05=50
P0.06=1
P0.08=1
P0.09=0.5

P9.00=0
P9.01=4
P9.02=1500
P9.03=0.75
P9.04=1.5
P9.05=1

P9.00=0
P9.01=4
P9.02=1500
P9.03=0.75
P9.04=1.5
P9.05=1

P9.16=0
P9.17=10
P9.18=0.5
PA.04=1
PA.05=100
PA.06=101
PA.13=010

P9.16=0
P9.17=10
P9.18=0.5
PA.04=1
PA.05=100
PA.06=101
PA.13=010