

Energia: 1.6.10E18 (Mac OS X), Board: "LaunchPad (Tiva C) w/ tm4c123 (80MHz)"

```
/Applications/Energia.app/Contents/Java/arduino-builder -dump-prefs -logger=machine -
hardware "/Applications/Energia.app/Contents/Java/hardware" -hardware "/Users/
danballard/Library/Energia15/packages" -tools "/Applications/Energia.app/Contents/
Java/tools-builder" -tools "/Applications/Energia.app/Contents/Java/hardware/tools/
msp430" -tools "/Users/danballard/Library/Energia15/packages" -built-in-libraries "/"
Applications/Energia.app/Contents/Java/libraries" -libraries "/Users/danballard/
Documents/Energia/libraries" -fqbn=energia:tivac:EK-TM4C123GXL -ide-version=10610
-build-path "/var/folders/vb/646wvykx2ms3625smztrs6jm0000gn/T/
buildd0b72ce2b4f77512eec99a6713fe17d.tmp" -warnings=none -
prefs=build.warn_data_percentage=75 -verbose "/Applications/Energia.app/Contents/
Java/examples/01.Basics/Blink/Blink.ino"
```

failed MSpanList_Insert 0x30d000 0xefdcc77294d9 0x0

fatal error: MSpanList_Insert

runtime stack:

runtime.throw(0x2ad50b)

 /usr/local/go/src/runtime/panic.go:491 +0xad fp=0x7ffeefbff400 sp=0x7ffeefbff3d0

runtime.MSpanList_Insert(0x2cb168, 0x30d000)

 /usr/local/go/src/runtime/mheap.c:692 +0x8f fp=0x7ffeefbff428 sp=0x7ffeefbff400

MHeap_FreeSpanLocked(0x2c7d60, 0x30d000, 0x100)

 /usr/local/go/src/runtime/mheap.c:583 +0x163 fp=0x7ffeefbff468

sp=0x7ffeefbff428

MHeap_Grow(0x2c7d60, 0x8, 0x0)

 /usr/local/go/src/runtime/mheap.c:420 +0x1a8 fp=0x7ffeefbff4a8

sp=0x7ffeefbff468

MHeap_AllocSpanLocked(0x2c7d60, 0x1, 0x0)

 /usr/local/go/src/runtime/mheap.c:298 +0x365 fp=0x7ffeefbff4e8

sp=0x7ffeefbff4a8

mheap_alloc(0x2c7d60, 0x1, 0x12, 0x0)

 /usr/local/go/src/runtime/mheap.c:190 +0x121 fp=0x7ffeefbff510

sp=0x7ffeefbff4e8

runtime.MHeap_Alloc(0x2c7d60, 0x1, 0x10000000012, 0xf989)

 /usr/local/go/src/runtime/mheap.c:240 +0x66 fp=0x7ffeefbff548 sp=0x7ffeefbff510

MCentral_Grow(0x2cfad8, 0x0)

 /usr/local/go/src/runtime/mcentral.c:197 +0x8b fp=0x7ffeefbff5b0

sp=0x7ffeefbff548

runtime.MCentral_CacheSpan(0x2cfad8, 0x0)

 /usr/local/go/src/runtime/mcentral.c:85 +0x167 fp=0x7ffeefbff5e8

sp=0x7ffeefbff5b0

runtime.MCache_Refill(0x309000, 0x12, 0x0)

 /usr/local/go/src/runtime/mcache.c:90 +0xa0 fp=0x7ffeefbff610 sp=0x7ffeefbff5e8

runtime.mcacheRefill_m()

 /usr/local/go/src/runtime/malloc.c:368 +0x57 fp=0x7ffeefbff630 sp=0x7ffeefbff610

runtime.onM(0x224f58)

 /usr/local/go/src/runtime/asm_amd64.s:273 +0x9a fp=0x7ffeefbff638

```
sp=0x7ffeefbff630
runtime.mallocgc(0x120, 0x1beba0, 0x0, 0x0)
    /usr/local/go/src/runtime/malloc.go:178 +0x849 fp=0x7ffeefbff6e8
sp=0x7ffeefbff638
runtime.newobject(0x1beba0, 0x309000)
    /usr/local/go/src/runtime/malloc.go:353 +0x49 fp=0x7ffeefbff710
sp=0x7ffeefbff6e8
runtime.newG(0x276ba)
    /usr/local/go/src/runtime/proc.go:233 +0x2a fp=0x7ffeefbff728 sp=0x7ffeefbff710
allocg(0x2ba660)
    /usr/local/go/src/runtime/proc.c:925 +0x1f fp=0x7ffeefbff738 sp=0x7ffeefbff728
runtime.malg(0x8000, 0x2ba700)
    /usr/local/go/src/runtime/proc.c:2106 +0x1f fp=0x7ffeefbff768 sp=0x7ffeefbff738
runtime.mpreinit(0x2baac0)
    /usr/local/go/src/runtime/os_darwin.c:137 +0x27 fp=0x7ffeefbff780
sp=0x7ffeefbff768
mcommoninit(0x2baac0)
    /usr/local/go/src/runtime/proc.c:201 +0xc9 fp=0x7ffeefbff7a8 sp=0x7ffeefbff780
runtime.schedinit()
    /usr/local/go/src/runtime/proc.c:138 +0x55 fp=0x7ffeefbff7d0 sp=0x7ffeefbff7a8
runtime.rt0_go(0x7ffeefbff800, 0x19, 0x7ffeefbff800, 0x0, 0x19, 0x7ffeefbff9d0,
0x7ffeefbffa08, 0x7ffeefbffa14, 0x7ffeefbffa24, 0x7ffeefbffa2e, ...)
    /usr/local/go/src/runtime/asm_amd64.s:95 +0x116 fp=0x7ffeefbff7d8
sp=0x7ffeefbff7d0
arduino-builder returned 2
```

Error compiling for board LaunchPad (Tiva C) w/ tm4c123 (80MHz).