

Matter Test Harness - Test Run Report

Test Run Information

Test Name	Status	Date	Time	Operator
UI_Test_Run_2023_06_19_13_06_52	passed	Jun 19, 2023	7:36:52 - 7:36:52 (6m2s)	Test

Result Statistics

Passed -1	Error -0	Cancelled -0	Failed -0	pending -0
-----------	----------	--------------	-----------	------------

Result Summary

S.No	Public ID	State	Time Elapsed
1	FirstChipToolSuite	Passed	6m2s
1.1	TC-OO-2.3	Passed	5m21s
1.1.1	Start chip-tool test	Passed	0m3s
1.1.2	1: Wait for the commissioned device to be retrieved	Passed	0m1s
1.1.3	2a: Send On Command	Not_applicable	0m0s
1.1.4	Wait 1000ms	Passed	0m0s
1.1.5	2b: Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.6	2b:Reads GlobalSceneControl attribute from DUT	Not_applicable	0m0s
1.1.7	3a:Sends OffWithEffect command to DUT	Not_applicable	0m0s
1.1.8	Wait 1000ms	Passed	0m0s
1.1.9	3b:Reads OnOff attribute from DUT	Not_applicable	0m0s

1.1.10	3b:Reads GlobalSceneControl attribute from DUT	Not_applicable	0m0s
1.1.11	4a:Sends OnWithRecallGlobalScene command to DUT	Not_applicable	0m0s
1.1.12	Wait 1000ms	Passed	0m0s
1.1.13	4b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.14	4b:Reads GlobalSceneControl attribute from DUT	Not_applicable	0m0s
1.1.15	5a:Sends OffWithEffect command to DUT	Not_applicable	0m0s
1.1.16	Wait 1000ms	Passed	0m0s
1.1.17	5b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.18	5b:Reads GlobalSceneControl attribute from DUT	Not_applicable	0m0s
1.1.19	5c:Send On Command	Not_applicable	0m0s
1.1.20	Wait 1000ms	Passed	0m0s
1.1.21	5d:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.22	5d:Reads GlobalSceneControl attribute from DUT	Not_applicable	0m0s
1.1.23	6a:Sends OffWithEffect command to DUT	Not_applicable	0m0s
1.1.24	Wait 1000ms	Passed	0m0s
1.1.25	6b:Reads OnOff attribute from DUT	Not_applicable	0m0s

1.1.26	6b:Reads GlobalSceneControl attribute from DUT	Not_applicable	0m0s
1.1.27	7a:Send On Command	Not_applicable	0m0s
1.1.28	Wait 1000ms	Passed	0m0s
1.1.29	7b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.30	7b:Reads GlobalSceneControl attribute from DUT	Not_applicable	0m0s
1.1.31	7c:Sends OnWithRecallGlobalScene command to DUT	Not_applicable	0m0s
1.1.32	Wait 1000ms	Passed	0m0s
1.1.33	7d:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.34	7d:Reads GlobalSceneControl attribute from DUT	Not_applicable	0m0s
1.1.35	8:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.36	8:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.37	9a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.38	9b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.39	9b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.40	9b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s

1.1.41	10a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.42	Wait 10000ms	Passed	0m8s
1.1.43	10b:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.44	Wait 10000ms	Passed	0m10s
1.1.45	10c:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.46	Wait 10000ms	Passed	0m10s
1.1.47	10d:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.48	10e:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.49	10e:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.50	10e:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.51	Wait 10000ms	Passed	0m10s
1.1.52	11a:Sends OffWithEffect command to DUT	Not_applicable	0m0s
1.1.53	11b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.54	11b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.55	11b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.56	Wait 10000ms	Passed	0m9s
1.1.57	12a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s

1.1.58	12b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.59	12b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.60	12b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.61	Wait 10000ms	Passed	0m10s
1.1.62	13a:Send On Command	Not_applicable	0m0s
1.1.63	13b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.64	13b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.65	13b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.66	Wait 10000ms	Passed	0m9s
1.1.67	14a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.68	Wait 10000ms	Passed	0m10s
1.1.69	14b:Send Off Command	Not_applicable	0m0s
1.1.70	14c:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.71	14c:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.72	14c:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.73	Wait 30000ms	Passed	0m29s

1.1.74	15:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.75	15:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.76	15:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.77	Wait 10000ms	Passed	0m10s
1.1.78	16a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.79	16b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.80	16b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.81	16b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.82	17a:Send On Command	Not_applicable	0m0s
1.1.83	Wait 10000ms	Passed	0m10s
1.1.84	17b:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.85	17c:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.86	17c:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.87	17c:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.88	Wait 40000ms	Passed	0m40s
1.1.89	17d:Reads OnOff attribute from DUT	Not_applicable	0m0s

1.1.90	17d:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.91	17d:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.92	Wait 10000ms	Passed	0m10s
1.1.93	18a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.94	18b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.95	18b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.96	18b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.97	19a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.98	Wait 10000ms	Passed	0m10s
1.1.99	19b:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.100	Wait 10000ms	Passed	0m10s
1.1.101	19c:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.102	19c:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.103	19c:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.104	20a:Send Off Command	Not_applicable	0m0s
1.1.105	20b:Reads OnOff attribute from DUT	Not_applicable	0m0s

1.1.106	20b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.107	20b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.108	21a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.109	Wait 10000ms	Passed	0m9s
1.1.110	21b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.111	21b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.112	21b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.113	22a:Send On Command	Not_applicable	0m0s
1.1.114	22b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.115	22b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.116	22b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.117	Wait 10000ms	Passed	0m9s
1.1.118	23a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.119	23b:Send Off Command	Not_applicable	0m0s
1.1.120	23c:Reads OnOff attribute from DUT	Not_applicable	0m0s

1.1.121	23c:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.122	23c:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.123	Wait 40000ms	Passed	0m40s
1.1.124	23d:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.125	23d:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.126	23d:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.127	24a:Sends OnWithTimedOff command to DUT	Not_applicable	0m0s
1.1.128	24b:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.129	24b:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.130	24b:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s
1.1.131	Wait 40000ms	Passed	0m40s
1.1.132	24c:Reads OnOff attribute from DUT	Not_applicable	0m0s
1.1.133	24c:Reads OnTime attribute from DUT	Not_applicable	0m0s
1.1.134	24c:Reads OffWaitTime attribute from DUT	Not_applicable	0m0s