

FamilyMart

Pest Inspection Report

Post-Inspection Report / MFM0125 Gelang Patah / 22 Jul 2025

Complete

Inspection	Post-Inspection Report
Store ID and Name	MFM0125 Gelang Patah
Tracker	Other pest
Inspector	Ain Nadhirah
Project Team PIC	Faiz
Project Team Present	Yes
Contractor PIC	Hometric Mr Yap
Contractor Present	Yes
Inspection Date	22.07.2025
Report Date	22.07.2025
Handover Date	22.07.2025

Findings

Findings #1

Location

Front store

Observations



Photo 1




Photo 2

Findings

Gaps at the wiring into the wall

Recommendation

To seal the gaps

Status

Pending




Photo 3

Findings #2

Location

Front store

Observations




Photo 4



Photo 5

Findings

Noted bird activity at the FamilyMart signage and at the TNB meter

Recommendation

To install bird spike

Status

Pending



Photo 6

Findings #3

LocationFront door

Observations




Photo 7




Photo 8



Photo 9

FindingsGlass door with gaps

RecommendationTo install door strip

StatusKIV

Gap is at minimum level, unable to install rubber strip

Findings #4

LocationBack store

Observations



Photo 10



Photo 11



Photo 12

FindingsGaps at the pipping into wall

RecommendationTo seal the gaps

StatusDone



Photo 13

Findings #5

LocationBackdoor

Observations



Photo 14



Photo 15



Photo 16



Photo 17

FindingsBackdoor bottom part rusty and damaged

RecommendationTo change a new door with door strip

StatusDone



Photo 18

Findings #6

LocationKitchen partition

Observations




Photo 19



Photo 20



Photo 21

FindingsPartition with gaps

RecommendationTo seal the gaps

StatusDone




Photo 22




Photo 23

Findings #7

Location Kitchen cabinet

Observations




Photo 24



Photo 25

Findings Cabinet with exposed partition

Recommendation To seal the gaps

Status Pending



Photo 26



Photo 27

Findings #8

Location Kitchen cabinet skirting

Observations




Photo 28




Photo 29

Findings Skirting with gaps

Recommendation To seal the gaps

Status Pending





Photo 30

Findings #9

Location

Small store room

Observations



Findings

Gaps underneath stairs

Recommendation

To seal the gaps

Status

Pending



Findings #10

Location

Above ceiling - Backroom

Observations



Findings


Gaps at the pipping

Recommendation

To seal the gaps

Status

Done



Findings #11

Location

Above ceiling - backroom

Observations



Photo 41



Photo 42

Findings

Gaps at the pipping to the wall

Recommendation

To seal the gaps

Status

Done

1 white pipe is closed left only 1 white pipe



Photo 43



Photo 44

Findings #12

Location

Above ceiling - backroom

Observations



Photo 45




Photo 46

Findings

Above ceiling - backroom

Recommendation

Gaps at the ceiling for the server wiring

Status

Pending




Photo 47

Findings #13

Location

Above ceiling - backroom

Observations



Photo 48




Photo 49




Photo 50

Findings

Gaps at the wiring to the wall

Recommendation

To seal the gaps

Status

Pending




Photo 51

Findings #14

Location

Above ceiling - in front of customer toilet

Observations



Photo 52




Photo 53

Findings

Gaps at the wiring

Recommendation

To seal the gaps

Status

Pending



Photo 54

Findings #15

Location

Above ceiling - OCC

Observations




Photo 55



Photo 56

Findings

Gaps at the ceiling down to OCC pipping

Recommendation

To seal the gaps

Status

Pending



Photo 57

Findings #16

Location

Small store room

Observations



Photo 58



Photo 59




Photo 60



Photo 61

Findings

New partition with gaps at the wall and floor

Recommendation

To seal the gaps

Status

New Findings

Findings #17

Location

External store

Observations



Photo 62



Photo 63



Photo 64



Photo 65

Findings

Additional location for bird spike

Recommendation

To install bird spike as well

Status

New Findings

Media summary

Photo 1




Photo 2



Photo 3



Photo 4



Photo 5



Photo 6




Photo 7




Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29




Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47



Photo 48




Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59




Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65