

July 30, 2021
03210730
New installation

DESCRIPTION	AMOUNT
Install new plenum coil	
M/N: / S/N:	
*pull vacuum	
*vacuum time; ~1 HR	
*flush copper lines with R-11	
*reseal openings with hardcast	
*recharge with R-410A	
Install new 110k BTU gas furnace	
*reseal openings with hardcast	
*rewire controls to furnace	
parts and labor	\$ 4,070.40
Notes: Email manufacturer warranty information to equipment owner. HPS provides a two-year labor warranty	
TOTAL	\$ 4,070.40

THANK YOU FOR YOUR BUSINESS!