

INVOICE

Code: CODE

DATE: December 29, 2021

INVOICE # 01211229

FOR: *heat pump wiring*

DESCRIPTION	AMOUNT
Heat pump not working properly Maintenance man worked on coil inside; reversing valve not working Troubleshooted heat pump system; reversing valve not wired right Recharged sytem to proper superheat level	
labor charge	\$ 497.00
-	
TOTAL	\$ 497.00

THANK YOU FOR YOUR BUSINESS!

