




The diagram shows two connectors, J12 and J5, with their pinout configurations. J12 is a 12-pin connector with pins labeled 1P to 12P. J5 is a 10-pin connector with pins labeled 1P to 10P. The pin numbers are listed below the connector symbols.

Pin	Label
1	1P
2	2P
3	3P
4	4P
5	5P
6	6P
7	7P
8	8P
9	9P
10	10P
11	11P
12	12P

J12  
Conn\_01x12

Pin	Label
1	1P
2	2P
3	3P
4	4P
5	5P
6	6P
7	7P
8	8P
9	9P
10	10P

J5  
Conn\_01x10



Rev: 1.0  
Id: 1/1