



leaving empty connections should work, incase it doesn't work then connect:  
pin 2 (p 12) - pin 1 (db out 1)  
pin 7 (p 12) - pin 8 (db out 1)

leaving empty connections should work, incase it doesn't work then connect:  
pin 1 (p 12) - pin 1 (db out 2)  
pin 8 (p 12) - pin 8 (db out 2)

