

SOP 4/2

2

Operate
Failures

- 1) double click on the icon
- 2) move the print first.

Cut the end flap off. Trim the label.

Check the camera is clean.

(put the sample on a piece of paper?)

Insert view window

As long as the 2D is in window.

Second press or binocs

Second press is the verification.

Keep pressure on cam
to stop light.

If OK, edged in purple.

MENU APPEARS

Choose plugin.

1) NUSSIA Pharmacy

2) GBI healthcare retail