

TVS

IFAD

IFAD MOTORS LTD

Head Office

IFAD TOWER, 07 Tejgaon I/A, Dhaka-1208.

DMS JOB NO

2756

Ref No:	Habiganj/Nov/327	FR SI NO#	327	Date:	05.11.2020
Zone Name:	Habiganj Zone	Engineer Name:	Md. Abdullah Al Zahed		
Approved by:	Prabir Biswas (Head of Service & Spare Parts)				

Customer Name:	MD. ISLAM MIAH		Mobile No:	01791140883	
Address:	SRIMONGOL, Mouvibazar		Dealer Name:	Kaderia Motors	
Customer Complaint:	CH NO Full #	MD6M14CL5K4NA0019	Present Kms #	560	
Prior pick-up	EN NO Full #	014NR41A0019	Model #	TVS KING	
	Sale Date #	28.10.2020		DURAMAX CNG	
	Date of Comp#	05.11.2020	1st PS Date	1st PS Kms	
	Date of Repair #	05.11.2020			

Free service information

1st Free Service		2nd Free Service		3rd Free Service	
Date	KMs	Date	KMs	Date	KMs
05.11.2020	560				

Observation:- We checked & found that IGNITION COIL WAS WEAK.


Reading ???

Action Taken:- New one IGNITION COIL WITH SUP. CAP 45 replaced.

Sl	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	64060370	IGNITION COIL WITH SUP. CA	1	N16008JG7A0		
2	64060370					
3						
4						
5						
6						

Failure Particular

For Head Office Use



Prabir Biswas
9/11/2020

Md. Abdullah Al Zahed
05-11-2020
Senior Service Engineer
IFAD MOTORS LTD.
Cell: 91791-227974

DMS Complete
Md. Sahar
07.11.2020

Note: Primary = 0.0042
Secondary = 12.7152