

TVS**PRODUCT PERFORMANCE FEEDBACK REPORT**
IFAD
 MOTORS LIMITED
IFAD MOTORS LTD

DMS NO: 13388

Head Office**IFAD Tower, Plot-7(New), Tejgoan Industrial Area, Dhaka-1208**

Ref.No: Sylhet/Nov/20/312

F.R SI No

312

Date:

20.11.2021

Zone Name: Sylhet

Engineer Name: Tisu Barua

Mchanic Name: Moin Uddin

Approved by: Kaushik Sarkar-COO(IFAD GROUP)

Customer Name: Tawsif Motors

Mobile No:

01726093570

Address:

Gotatikor, Sylhet.

Dealer Name:

Tawsif Motors

Customer Complain:-

CH NO Full #

MD6M14CL7M4C00072

Present Km

60

Self Start Problem

EN NO Full #

OL4CM4000355

Model #

TVS King Duramax
plus

Sale Date #

Date of Comp#

1st PS Date

1st PS Kms

Date of Repair#

Free service information

1st Free Service

2nd Free Service

3rd Free Service

Date

KMs

Date

KMs

Date

KMs

Obserbation:- We checked & found that the TCI unit is not working.

Action Taken:- Require to replace this parts under warranty for your approval.

Failure Particular


SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G4060400	TCI UNIT W/O FMS	1			
2						
3						
4						

Failure Parts Photo**For Head Office Use**

Head of Service

Engineer

DMS



09/12/21

23/11/2021

23/11/2021
DMS Complete.