



IFAD MOTORS LTD

Head Office

IFAD TOWER, 07 Tejgaon I/A, Dhaka-1208.

DMS JOB NO

2309

Ref.No: Habiganj/August/316

F.R SI NO#

316

Date:

20.08.2020

Zone Name: Habiganj Zone

Engineer Name:

Md. Abdullah Al Zayed

Approved by: Prabir Biswas (Head of Service & Spare Parts)

Customer Name: Md. Mijanur Rahman

Mobile No:

01738310442

Address: Moulvibazar

Dealer Name:

Kaderia Motors

Customer Complain:-

CH NO Full #

MD6M14CL3K4NA0018

Present Kms #

180

Poor pick -up

EN NO Full #

0L4NK46A0018

Model #

TVS KING
DURAMAX CNG

Sale Date #

17.08.2020

Date of Comp#

20.08.2020

1st PS Date

1st PS Kms

Date of Repair #

20.08.2020

Free service information

1st Free Service

2nd Free Service

3rd Free Service

Date

KMs

Date

KMs

Date

KMs

20.08.2020

180

Observation:- We checked & found that IGNITION COIL WAS WEAK.


Reading

Action Taken:- New one IGNITION COIL WITH SUP. CAP 4S replaced.

Failure Particular

| SL | Part NO | Part Name | Qty | Vendor code | Approved | Rejected |
|----|----------|-------------------------------|---------|---------------|----------|----------|
| 1 | G4060370 | IGNITION COIL WITH SUP. CAP 4 | 1 | NIG011909A010 | | |
| 2 | G4060250 | " | 01 | | | |
| 3 | | | Any one | | | |
| 4 | | | | | | |
| 5 | | | | | | |
| 6 | | | | | | |

Failure Parts Photo



For Head Office Use

Prabir Biswas
14/9/2020 -
Replace from a new vehicle
spare order in 10th LC
once spare received new
part to be
fitted in that
vehicle.
09.07.2020
DMS complete

2/09/2020