

PRODUCT PERFORMANCE FEEDBACK REPORT

TVS



IFAD MOTORS LTD

Head Office

DMS JOB NO

3082

Holding No:07, 1st Floor, IFAD Tower, Tejgaon Industrial Area,Dhaka-1208.

Ref.No:	Faridpur /JANUARY-2021 /	F.R SI NO#		Date:	20/01/2021	
Zone Name:	Faridpur	Engineer/Mechanic Name:	Tomal			
Approved by:	Prabir Biswas, Head of Service & Spare Parts					
Customer Name:	RINA KHATUN	Mobile No:	01892-874420			
Address:	Faridpur SADAR,FARIDPUR	Dealer Name:	Hello Bike			
Customer Complain:-	CH NO Full #	MD6M14LA5L4C00262	Present Kms #	546		
Self Start Problem	EN NO Full #	AK4CL4708352	Model #	Tvs King Deluxe LPG		
	Sale Date #	3/12/2020				
	Date of Comp#	10.12.2020	1st PS Date	1st PS Kms		
	Date of Repair #	12.12.2020				
	Free service information					
1st Free Service		2nd Free Service		3rd Free Service		
Date	KMs	Date	KMs	Date	KMs	
12.12.2020	565					
Engineer Comment : We check & found that armatour coil problem .						
Action Taken:- Required this parts replcement under Warranty.						
Failure Particular						
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	G4060170	Stator Motor	01			
2						
3						
4						
5						
6						
Failure Parts Photo			For Head Office Use			
						

20/01/2021

Prabir Biswas
31.01.2021
DMS Complete