

TVS

Delivery order date 09/05/22

PRODUCT PERFORMANCE FEEDBACK REPORT

TVS

IFAD MOTORS LTD

DMS NO:

Head Office

9423

IFAD Tower, Plot-7(New), Teigoan Industrial Area, Dhaka-1208

Ref.No: April-200

F.R SI NO#

200

Date:

25.04.2022

Zone Name: Cumilla/ B.Baria

Engineer Name: Md.Pabel Sarker

Mchanic Name: Shimol Hossain

Approved by: Prabir Biswas (Head of Service, Spare Parts & Production)

Customer Name: Monir Hossain

Mobile No:

+8801647808487

Address:

Chandora, Bijoy nagur, B.Baria

Dealer Name:

Modina Motors

Customer Complain:-

Highly oil consumption

CH NO Full #

MD6M14CL9L4N00028

Present Km

19540

EN NO Full #

OL4NL4600056

Model #

TVS King Duramax plus

Sale Date #

22.04.2021

Date of Comp#

24.04.2022

1st PS Date

1st PS Kms

Date of Repair#

Free service information

1st Free Service

2nd Free Service

3rd Free Service

Date

KMs

Date

KMs

Date

KMs

27.05.2021

1800

29.08.2021

8,530

20.11.2021

14008

Observation:-

we checked & found that highly oil consumption per 250 ml.

Action Taken:- Require to replace this parts under warranty for approval.

Failure Particular

SL	Part NO.	Part Name	Qty	Vendor code	Approved	Rejected
1	G4020130	Piston Std.	01	A-Done		1100
2	G4011470	Cylinder block comp	01	DMS (stock does not exists for part)		
3						
4						

Failure Parts Photo

For Head Office Use

Head of Service

Engineer

DMS

Mitu Sahar
26.04.2022
 DMS
 Complete.