








Transformers
Secondary Side
Connections



Transformer Output Sel
for Delta/Star Output
220V / 380V



To Soft Start Phase
Voltage Inputs

To Soft Start Motor
Inputs

