







## Attenuation and BW change buttons




## Check if IC101 output indicates overvoltage



## 1s delay on turn-off

Q101 - reverse D with S...  
R165 -> 10k  
R163 -> 1M



Sheet: /Buttons\_indication/  
File: Buttons\_indication.kicad\_sch

### Title:

Size: A4

Date:

KiCad E.D.A. 9.0.0

Rev:

Id: 5/5