


The diagram shows the following connections:

- GPIO1** (pin 1) to **PWM** (pin 6)
- RST** (pin 2) to **GPIO2** (pin 7)
- CS** (pin 3) to **UART-RX** (pin 8)
- SCK** (pin 4) to **UART-TX** (pin 9)
- MISO** (pin 5) to **SCL** (pin 10)
- MOSI** (pin 6) to **SDA** (pin 11)
- 3.3V** (pin 7) to **+5V_MIKROE** (pin 12)
- GND** (pin 8) to **GND** (pin 13)

Additional labels include "U1 CLICK BOARD" at the top and "GND" at the bottom right.

Notes	Pin					Pin	Notes
	NC	1	AN	PWM	16	R/T	Read/Transmit
	NC	2	RST	INT	15	NC	
	NC	3	CS	RX	14	TX	UART TX
	NC	4	SCK	TX	13	RX	UART RX
	NC	5	MISO	SCL	12	NC	
	NC	6	MOSI	SDA	11	NC	
	NC	7	3.3V	5V	10	5V	Power supply
Ground	GND	8	GND	GND	9	GND	Ground