



ools



Microsoft Store



Snipping Tool



Employee limit exceeded

Your current plan can accommodate for up to 50 employees. You are exceeding the limit by attempting to sign in as the 1 person for the last 24 hours.

Please [select a plan](#) to match your business, or [remove](#) inactive employees.

Select a plan

List of employees

Ticket Control



Ticket Code

Reference No

Degree

Created By

250

TI410

97002

Leads to Note

Ahmed Ghattas

Description:

In waterproofing roof system, there is no protection layer between waterproofing membrane layer and thermal insulation(inspection team will check at site). In [REDACTED] waterproofing roof system, there is no protection layer between waterproofing membrane layer and thermal insulation(inspection team will check at site). In [REDACTED] waterproofing roof system, there is no protection layer between waterproofing membrane layer and thermal insulation(inspection team will check at site). In [REDACTED] waterproofing roof system, there is no protection layer between waterproofing membrane layer and thermal insulation(inspection team will check at [REDACTED] site).

Select Degree ...



Transfer To...

☐ Receiving Data

Cancel

Submit

RD5 Status

Activity

Action

Update

Update

Update

Update