

Floor robot – Terminal box at axis 3

	ROW 1		ROW 2	
N.C.	1		1	N.C.
N.C.	2		2	N.C.
N.C.	3		3	N.C.
N.C.	4		4	N.C.
SHIELD	5		5	SHIELD
N.C.	6		6	N.C.
PROFI Neg Tools (Green)	7		7	PWR GND Valve (Black+White)
PROFI Pos Tools (Red)	8		8	24 V Valve (Brown+Blue)
PROFI Neg Valve (Green)	9		9	PWR GND Tools (Brown)
PROFI Pos Valve (Red)	10		10	24 V Tools (Blue)
PROFI Neg IN (Green)	11		11	PWR GND IN (Brown)
PROFI Pos IN (Red)	12		12	24 V IN (Blue)