



During testing, the linear driver on the MOD12003 was shown not to be robust enough; it lost bias during an abusive "file" test (rapidly shorting/opening the output by rubbing a wire over a file). This is an updated driver circuit to be patched into Rev A of MOD12003.

FID FID1
FIDUCIAL—1.5mm

FID FID2
FIDUCIAL—1.5mm

CC0

Title: MOD12003 LINEAR DRIVER BODGE

Rev: 1

Sheet: /

Id: 1/1

Semianalog

Date: 2016-02-25