



Hall Sensor Power Scenarios:
* Passthrough mode enabled: Hall sensors connected to actuator board.
Hall sensors can be powered from actuator board
* Passthrough mode disabled: Hall sensors disconnected from actuator board.
Hall sensors can be powered from actuator board
* Actuator-only mode: Don't care about hall power
* Motor-only mode: Need to bring hall power




Do we care about being able to run from an actuator with broken hall power?
We could just diode-or in power, is there ever a case where we need to be able to disable hall power completely??
Do we want to siphon hall power for charging?

ACTUATOR connector pinouts are REVERSED
so we can use straight-through cables

To Actuator Board





To Motor



TITLE			
SIZE	DWG NO	REV	
B	TBD	Schematic1 -	
SCALE	SHEET	of	11/07/2024:09:26
1 : 1	1	1	

DRAWN BY
HAL GLENN







TITLE			
SIZE	DWG NO	REV	
B	TBD	G004623_Power_Prog_Board_RevA	
SCALE	SHEET	of	11/07/2024:09:35
1 : 1	3	3	

DRAWN BY
HAL GLENN









TITLE			
<Drawing Name Here>			
SIZE	DWG NO	SHEET NAME	REV
B	TBD	G005769rA_BLDC_Test_Tool	<X>
SCALE	SHEET		09/07/2024:18:30
1 : 1	7 of 7		