



NOTES:

1. Material - Zinc Coated Sheet Steel (~28 GA)
2. Attach ground lead from AC receptacle to under side of mounting plate using ring terminal and hot plate mounting screw.