


Notes:
PUL= Driving Plus
DIR =Direction Ctrl
ENA =Enable

3D-printer Stepper Motor Control

H.S.. Lam, Ver 1.1, 3Nov 2020



GPIO

Direction	Value
<input type="checkbox"/> 17-03	<input type="checkbox"/> 17-04
<input type="checkbox"/> 17-05	<input type="checkbox"/> 17-06
<input type="checkbox"/> 17-07	<input checked="" type="checkbox"/> 17-08 ENA
<input type="checkbox"/> 17-09	<input checked="" type="checkbox"/> 17-10 PLUSE

Set

Reset

Read

Write