

BOM Report

생성일: 2026-02-17 00:54

Lvl	Part No	I.S	MR	Document	Check Out	Change	R	Parent Part No	Parent Name
0	LSEL6335F.ARS11LGA@CVZ.EKHQ					ModelECO	B	LSEL6335F.ARS11LGA@CVZ.EKHQ	LSEL6335F.ARS11LGA@CVZ.EKHQ
.1	ABU7457321510		1.6	ysKoeDgWca2lO7ruqpMyY2			B	LSEL6335F.ARS11LGA@CVZ.EKHQ	LSEL6335F.ARS11LGA@CVZ.EKHQ
..2	ABU7457370410		1.3	x_SYXleqV-Gk-qOmwwFMyS			B	ABU74573215ABU74573704	ABU74573215ABU74573704
...3	ABU7387323310		1.1	QQMeEW2lh7LwgYdpJy35nb			B	ABU74573704ABU73873233	ABU74573704ABU73873233
....4	MGJ6458400410		1.0	ODI6Os4RdxkBv-V5Lh8JmV			B	ABU73873233MGJ64584004	ABU73873233MGJ64584004
.....5	MGJ6436660410		1.2	qsdNLCWQObi9pbPYwu9RxT			B	MGJ64584004MGJ64366604	MGJ64584004MGJ64366604
.....6	RAA3399672610			bAIT6Gw4OhXq6PQ0KaUmBX			B	MGJ64366604RAA33996726	MGJ64366604RAA33996726
....4	MGJ6442930620		1.1	ceKE4mTtN9diSuW0KaUmFY			B	ABU73873233MGJ64429306	ABU73873233MGJ64429306
.....5	RAA3399670710			TkyEve3bZ2qBfaC0KaUmBX			B	MGJ64429306RAA33996707	MGJ64429306RAA33996707
.....5	RCL3008130120						B	MGJ64429306RCL30081301	MGJ64429306RCL30081301
....4	MGJ6442970130		1.1	GtqjtrQXo1sTNNpD5xFsoL			B	ABU73873233MGJ64429701	ABU73873233MGJ64429701
.....5	RAA3399671510			WsN4a0xAXx8ZDii0KaUmBX			B	MGJ64429701RAA33996715	MGJ64429701RAA33996715
....4	AGU7500890440		1.1	q-pdRY4WVB9n7pas4m2TnB			B	ABU73873233AGU75008904	ABU73873233AGU75008904
.....5	MGJ6442960310		1.0	brNIqL48uDEtSiBIEmmTJU			B	AGU75008904MGJ64429603	AGU75008904MGJ64429603
.....6	RAA3399671110			VJfekpVO3UzNReS0KaUmBX			B	MGJ64429603RAA33996711	MGJ64429603RAA33996711
.....5	4810W1A282D20		1.1	BW-vVYplc8tylINV0faEEo2			B	AGU750089044810W1A282D	AGU750089044810W1A282D
.....6	RAA3174961110		1.1	VJBMi5aySB69HblIvFMNOq			B	4810W1A282DRAA31749611	4810W1A282DRAA31749611
.....6	RCL3008100120				정도훈(dohhoon.jeong)		B	4810W1A282DRCL30081001	4810W1A282DRCL30081001
....4	4810W1N019A50		1.1	3mKysvwjteJDHuSZvq-iX			B	ABU738732334810W1N019A	ABU738732334810W1N019A
.....5	RAA3174960320		1.2	xjm0fRCW-owl3eQqvMEf5a			B	4810W1N019ARA31749603	4810W1N019ARA31749603
.....5	RCL3008100130				정도훈(dohhoon.jeong)		B	4810W1N019ARCL30081001	4810W1N019ARCL30081001
...3	RAB3337290520		1.4				B	ABU74573704RAB33372905	ABU74573704RAB33372905
....4	RAB3341680110		1.0	IN0FkrvXzp7Zy2i0KaUllv			B	RAB33372905RAB33416801	RAB33372905RAB33416801
....4	RAB3594960120				정도훈(dohhoon.jeong)		B	RAB33372905RAB35949601	RAB33372905RAB35949601
S	RAB3594960220						S	RAB33372905RAB35949602	RAB33372905RAB35949602
....4	RAB3532970130			S2Y5i2keQWQ28K9Kadlnhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB35329701	RAB33372905RAB35329701
....4	RAB3337090140			Ole8shNqyLvbb820Z4Uonhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB33370901	RAB33372905RAB33370901
....4	RAB3337100150			2nV3FJQQXxP9855Kadlnhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB33371001	RAB33372905RAB33371001
....4	RAB3337110260			iGqRWbk0AwF8ALU0Kadlnhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB33371102	RAB33372905RAB33371102
S	RAB3337110160						S	RAB33372905RAB33371101	RAB33372905RAB33371101
....4	RAB3337060270			j3C9RCStQAJn3W5SKadlnhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB33370602	RAB33372905RAB33370602
S	RAB3337060170						S	RAB33372905RAB33370601	RAB33372905RAB33370601
....4	RAB3337070180			tl0eJnUSr4xK9P80Kadlnhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB33370701	RAB33372905RAB33370701
....4	RAB3349020190			iGis1lefrllyZm485L3Vdhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB33490201	RAB33372905RAB33490201
....4	RAB33371901100			4rlGUUIC1ZUC3550Z4Uonhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB33371901	RAB33372905RAB33371901
....4	RAB33371401110			NbJnPtl3SZ2q4SC0Kadlnhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB33371401	RAB33372905RAB33371401
....4	RAB33372001120			0QWLEipk0GX8V4590Kadlnhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB33372001	RAB33372905RAB33372001
....4	RAB35329802130			jpXrLnBmfOON5V4ZKadlnhoon.jeong)	정도훈(dohhoon.jeong)		B	RAB33372905RAB35329802	RAB33372905RAB35329802

S	RAB35329801 130			S	RAB33372905 RAB35329801
....4	RAB33377701 140	1.0	u9gMWaaFT4oMwBE0KaUloW	B	RAB33372905 RAB33377701
....4	RAB33590401 150	1.0	h8Ea7MqLuhSpBr60KaUlos	B	RAB33372905 RAB33590401
....4	RAB37010601 160		vNgbxLgJx81Zb5CkaUmh0n.jeong)	B	RAB33372905 RAB37010601
....4	RAB33373104 170	1.0		B	RAB33372905 RAB33373104
.....5	RAB33416801 10	1.0	IN0FkrvXzp7Zy2i0KaUllv	B	RAB33373104 RAB33416801
.....5	RAB35949601 20		정도훈(dohhoon.jeong)	B	RAB33373104 RAB35949601
.....5	RAB33370901 30		Ole8shNqyLvbn90KaUmh0n.jeong)	B	RAB33373104 RAB33370901
.....5	RAB33371101 40		hsfaZJNYKcti850KaUmh0n.jeong)	B	RAB33373104 RAB33371101
.....5	RAB33416901 50	1.0	cgKRPg2W8bOJInk0KaUmOF	B	RAB33373104 RAB33416901
.....5	RAB33370601 60		if1ITu6RnYHUc850KaUmh0n.jeong)	B	RAB33373104 RAB33370601
.....5	RAB33370701 70		tl0eJnUsr4xK9P8KaUmh0n.jeong)	B	RAB33373104 RAB33370701
.....5	RAB33490201 80		iGis1IefrllYzm485KaUmh0n.jeong)	B	RAB33373104 RAB33490201
.....5	RAB33371901 90		4rlGUUIC1ZUC350KaUmh0n.jeong)	B	RAB33373104 RAB33371901
....4	MAF63587801180		정도훈(dohhoon.jeong)	B	RAB33372905 MAF63587801
S	RAB33372902 20			S	ABU74573704RAB33372902
..2	MFZ64539501 20		Swr7YMLrr-zODpVKHb_2qH	B	ABU74573215MFZ64539501
..2	EAQ62881201 30		6NEYHQa-2nP5AMU3TbVVAZQUEZ(samaBtha.v...	B	ABU74573215EAQ62881201
..2	3920W1N013A 40		0hyUNPpL9AbxuwXbZ33MC8	B	ABU745732153920W1N013A
..2	EBG61305805 50		RYGwrU2v1w085KaUmh0n.jeong)	B	ABU74573215EBG61305805
..2	MJH6377650160	1.1	470WrtOMKLcys9e5mqww_b	B	ABU74573215MJH63776501
...3	8PBT0110001 30			B	MJH637765018PBT0110001
..2	MCZ6353200170	1.3	VAr3EtOdpmXkruC0KaUmIK	B	ABU74573215MCZ63532001
...3	RAA34017101 10			B	MCZ63532001RAA34017101
...3	RCL30093001 20		정도훈(dohhoon.jeong)	B	MCZ63532001RCL30093001
..2	5230W1N001G 80		9VflLrpP58LnPxQ0KaUlqb	B	ABU745732155230W1N001G
..2	MAZ6476430190	1.2	y7UJe0S1ERNerU0KaUm8s	B	ABU74573215MAZ64764301
...3	RAA34077401 10			B	MAZ64764301RAA34077401
...3	RCL30092901 20			B	MAZ64764301RCL30092901
..2	MEE62865003 100		PNKWcsCGXQFlxJD6c0kGjR	B	ABU74573215MEE62865003
..2	MEE62306506 110		-R2sGepMqf2L2H8Myska.kim)	B	ABU74573215MEE62306506
S	MEE62306504 110			S	ABU74573215MEE62306504
..2	MAZ63491303120	1.2	kwL2bnU_SaUaCEi2BmgU8l	B	ABU74573215MAZ63491303
...3	RAA31629925 10		2wAYWJtjof4joS80KaUlv0	B	MAZ63491303RAA31629925
...3	RCL30093701 20			B	MAZ63491303RCL30093701
..2	1SZZW2A004E130		RnAXuaknArBt_ywVaxncol	B	ABU745732151SZZW2A004E
Q	1SZZW2A004E130		RnAXuaknArBt_ywVaxncol	Q	ABU745732151SZZW2A004E
Q	1SZZW2A004E130		RnAXuaknArBt_ywVaxncol	Q	ABU745732151SZZW2A004E

Q	1SZZW2A004E130		RnAXuaknArBt_ywVaxncol	Q	ABU745732151SZZW2A004E
Q	1SZZW2A004E130		RnAXuaknArBt_ywVaxncol	Q	ABU745732151SZZW2A004E
Q	1SZZW2A004E130		RnAXuaknArBt_ywVaxncol	Q	ABU745732151SZZW2A004E
.1	AEV73249605 110		hF_hVQbsGqtJJ4GKZTppbl	B	LSEL6335F.ARS11073249605BKHQ
S	AEV73249603 110			S	LSEL6335F.ARS11073249603BKHQ
.1	MEV65114903130		autJKd3mEwX0wlle2LxIHL	B	LSEL6335F.ARS11073249603BKHQ
.1	AGL30243713 140	1.6	s473HHvTcSKsS9vNPXEt9C	B	LSEL6335F.ARS11073249603BKHQ
..2	MGC6381980410	1.1		B	AGL30243713 MGC63819804
...3	RAA33956510 10			B	MGC63819804 RAA33956510
...3	RCL30078401 20			B	MGC63819804 RCL30078401
S	MGC6381980710			S	AGL30243713 MGC63819807
..2	MAZ6456980120	1.1	HTokjBuq3TCXZnE0KaUmf9	B	AGL30243713 MAZ64569801
...3	RAA33999001 10			B	MAZ64569801 RAA33999001
...3	RCL30080501 20			B	MAZ64569801 RCL30080501
..2	MJH66314301 30	1.1	lZoTinJx0nvTMGG0KaUm9Z	B	AGL30243713 MJH66314301
...3	RCL30780501 10			B	MJH66314301 RCL30780501
...3	RCL30078601 20		정도훈(dohhoon.jeong)	B	MJH66314301 RCL30078601
..2	EAG32629305 40		ZQwuC_jtwsGVOr_Njc-j7F	B	AGL30243713 EAG32629305
..2	EBG51439305 50		TpjewlGKQE68VCC0KaUmei	B	AGL30243713 EBG51439305
..2	EAU62862907 60	1.1	YvPIYADfGOgFuoAnm_oY_w	B	AGL30243713 EAU62862907
...3	EAU64063802 10		QM-Vm8ReqpX2el5467mhGi	B	EAU62862907 EAU64063802
...3	MAZ6444460220		MwdEPvvgVFGyXcswGfrVVZ	B	EAU62862907 MAZ64444602
...3	MBJ62582002 30		khxeUb9y_uWl1bkvcrVhCn	B	EAU62862907 MBJ62582002
...3	EBF64567702 40		FsPg4yqntRr8MrWouu4lsc	B	EAU62862907 EBF64567702
..2	EBR31737803 70	1.9	7IXqFAglbuHLujLLPdZLuQ	B	AGL30243713 EBR31737803
...3	EAM6578890110			B	EBR31737803 EAM65788901
Q	EAM6578890110			Q	EBR31737803 EAM65788901
...3	EBJ60850901 20		Q5c0FlhflWD3xnE0KaUmD5	B	EBR31737803 EBJ60850901
Q	EBJ60850901 20		Q5c0FlhflWD3xnE0KaUmD5	Q	EBR31737803 EBJ60850901
...3	EBC62298201 30			B	EBR31737803 EBC62298201
Q	EBC62298201 30			Q	EBR31737803 EBC62298201
Q	EBC62298201 30			Q	EBR31737803 EBC62298201
...3	EAH63473601 40		ANDREA CARDENAS(andreaCard...	B	EBR31737803 EAH63473601
Q	EAH63473601 40		ANDREA CARDENAS(andreaCard...	Q	EBR31737803 EAH63473601
Q	EAH63473601 40		ANDREA CARDENAS(andreaCard...	Q	EBR31737803 EAH63473601
Q	EAH63473601 40		ANDREA CARDENAS(andreaCard...	Q	EBR31737803 EAH63473601
...3	OCE108XH61850			B	EBR31737803 OCE108XH618
Q	OCE108XH61850			Q	EBR31737803 OCE108XH618

Q	OCE108XH61850			Q	EBR31737803 OCE108XH618
...3	EBB61801501 60		정도훈(dohhoon.jeong)	B	EBR31737803 EBB61801501
Q	EBB61801501 60		정도훈(dohhoon.jeong)	Q	EBR31737803 EBB61801501
...3	EAN6100160170			B	EBR31737803 EAN61001601
Q	EAN6100160170			Q	EBR31737803 EAN61001601
...3	0RJ0151J691 80			B	EBR31737803 0RJ0151J691
Q	0RJ0151J691 80			Q	EBR31737803 0RJ0151J691
Q	0RJ0151J691 80			Q	EBR31737803 0RJ0151J691
...3	0RH1002C62290			B	EBR31737803 0RH1002C622
Q	0RH1002C62290			Q	EBR31737803 0RH1002C622
Q	0RH1002C62290			Q	EBR31737803 0RH1002C622
...3	EBB63143901 100			B	EBR31737803 EBB63143901
Q	EBB63143901 100			Q	EBR31737803 EBB63143901
Q	EBB63143901 100			Q	EBR31737803 EBB63143901
Q	EBB63143901 100			Q	EBR31737803 EBB63143901
Q	EBB63143901 100			Q	EBR31737803 EBB63143901
Q	EBB63143901 100			Q	EBR31737803 EBB63143901
Q	EBB63143901 100			Q	EBR31737803 EBB63143901
...3	0DRSD00308A110			B	EBR31737803 0DRSD00308A
Q	0DRSD00308A110			Q	EBR31737803 0DRSD00308A
Q	0DRSD00308A110			Q	EBR31737803 0DRSD00308A
...3	EAX69471801 120	1.2	kIF_WPYAn-SDQ-LaaZZ8NA	B	EBR31737803 EAX69471801
...3	EAE64001601 130			B	EBR31737803 EAE64001601
Q	EAE64001601 130			Q	EBR31737803 EAE64001601
...3	6630VK09815 140			B	EBR31737803 6630VK09815
Q	6630VK09815 140			Q	EBR31737803 6630VK09815
...3	0CF2221Y47A 150		XjO8eupHVyjl6HQ0KaUIQE	B	EBR31737803 0CF2221Y47A
Q	0CF2221Y47A 150		XjO8eupHVyjl6HQ0KaUIQE	Q	EBR31737803 0CF2221Y47A
...3	0ILNRKE010A 160			B	EBR31737803 0ILNRKE010A
Q	0ILNRKE010A 160			Q	EBR31737803 0ILNRKE010A
...3	6102FC1158D 170			B	EBR31737803 6102FC1158D
Q	6102FC1158D 170			Q	EBR31737803 6102FC1158D
...3	0RJ2001D477 180			B	EBR31737803 0RJ2001D477
Q	0RJ2001D477 180			Q	EBR31737803 0RJ2001D477
...3	0CG2220U630190			B	EBR31737803 0CG2220U630
Q	0CG2220U630190			Q	EBR31737803 0CG2220U630
...3	0RJ2202D677 200			B	EBR31737803 0RJ2202D677
Q	0RJ2202D677 200			Q	EBR31737803 0RJ2202D677

...3	0RH0102C622210		B	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
Q	0RH0102C622210		Q	EBR31737803 0RH0102C622
...3	EAH64252901 220		B	EBR31737803 EAH64252901
Q	EAH64252901 220		Q	EBR31737803 EAH64252901
...3	OCE476EK638 230		B	EBR31737803 OCE476EK638
Q	OCE476EK638 230		Q	EBR31737803 OCE476EK638
...3	OILI817000H 240		B	EBR31737803 OILI817000H
Q	OILI817000H 240		Q	EBR31737803 OILI817000H
Q	OILI817000H 240		Q	EBR31737803 OILI817000H
S	EAV65093201 240		S	EBR31737803 EAV65093201
...3	0RH8200C422250		B	EBR31737803 0RH8200C422
Q	0RH8200C422250		Q	EBR31737803 0RH8200C422
...3	EAG64172601 260	1.0	B	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
Q	EAG64172601 260	1.0	Q	EBR31737803 EAG64172601
S	EAG64172603 260		S	EBR31737803 EAG64172603
...3	EAG64310007 270		B	EBR31737803 EAG64310007
Q	EAG64310007 270		Q	EBR31737803 EAG64310007

...3	0CZZQE2022B280		B	EBR31737803 0CZZQE2022B
Q	0CZZQE2022B280		Q	EBR31737803 0CZZQE2022B
...3	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	B	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
Q	EAH61515501 290	I5Gms5ndsv0LFW0QAVFrs11.dave)	Q	EBR31737803 EAH61515501
...3	EAE63065701 300		B	EBR31737803 EAE63065701
Q	EAE63065701 300		Q	EBR31737803 EAE63065701
...3	6630VM01111310		B	EBR31737803 6630VM01111
Q	6630VM01111310		Q	EBR31737803 6630VM01111
...3	0RJ0102G676 320		B	EBR31737803 0RJ0102G676
Q	0RJ0102G676 320		Q	EBR31737803 0RJ0102G676
...3	0RH3301C422330		B	EBR31737803 0RH3301C422
Q	0RH3301C422330		Q	EBR31737803 0RH3301C422
Q	0RH3301C422330		Q	EBR31737803 0RH3301C422
...3	0FS3151B9AD 350		B	EBR31737803 0FS3151B9AD
Q	0FS3151B9AD 350		Q	EBR31737803 0FS3151B9AD
...3	EAE65942801 360		B	EBR31737803 EAE65942801
Q	EAE65942801 360		Q	EBR31737803 EAE65942801
...3	SS0000008AA 370		B	EBR31737803 SS0000008AA
...3	7245ZB0004A 380		B	EBR31737803 7245ZB0004A
...3	RAC31704501 390		B	EBR31737803 RAC31704501
...3	SS0000019AA 400		B	EBR31737803 SS0000019AA
...3	EBB61801402 420		B	EBR31737803 EBB61801402
Q	EBB61801402 420		Q	EBR31737803 EBB61801402
Q	EBB61801402 420		Q	EBR31737803 EBB61801402
Q	EBB61801402 420		Q	EBR31737803 EBB61801402
Q	EBB61801402 420		Q	EBR31737803 EBB61801402
..2	MJH6632290180	Zs2lg7INPaChVLM0KaUm9v	B	AGL30243713 MJH66322901
..2	MEG6447880190	yi9IqWZFXnMMSWWvHY8M8M	B	AGL30243713 MEG64478801

..2	6877W1N024F100		Gyc1GkyhMbXn4ONCveeHZn	B	AGL30243713 6877W1N024F
..2	FAB30162501 110		bpaY96LYkr1yjoGASKKFd2	B	AGL30243713 FAB30162501
..2	1TTL0403118 120		qeZLvCTHwMW1IJ2Kn0zh9G	B	AGL30243713 1TTL0403118
..2	1TPL0302418 130		5LVLZhxtG28VVQtVibdl	B	AGL30243713 1TPL0302418
..2	1TTL0402418 140		XhHe7pwalRF_3t-IVwAcYc	B	AGL30243713 1TTL0402418
Q	1TTL0402418 140		XhHe7pwalRF_3t-IVwAcYc	Q	AGL30243713 1TTL0402418
Q	1TTL0402418 140		XhHe7pwalRF_3t-IVwAcYc	Q	AGL30243713 1TTL0402418
Q	1TTL0402418 140		XhHe7pwalRF_3t-IVwAcYc	Q	AGL30243713 1TTL0402418
Q	1TTL0402418 140		XhHe7pwalRF_3t-IVwAcYc	Q	AGL30243713 1TTL0402418
Q	1TTL0402418 140		XhHe7pwalRF_3t-IVwAcYc	Q	AGL30243713 1TTL0402418
Q	1TTL0402418 140		XhHe7pwalRF_3t-IVwAcYc	Q	AGL30243713 1TTL0402418
..2	4000W4A003A150	1.2		B	AGL30243713 4000W4A003A
...3	1SZZJJ3007A 10			B	4000W4A003A1SZZJJ3007A
...3	1WZZJJ3003A 20			B	4000W4A003A1WZZJJ3003A
Q	4000W4A003A150	1.2		Q	AGL30243713 4000W4A003A
Q	4000W4A003A150	1.2		Q	AGL30243713 4000W4A003A
..2	MJH66251901160	1.2	Lvg8dgnePEFBzgO0KaUlvh	B	AGL30243713 MJH66251901
...3	RAA31737261 10		wVVCuwVCHQM1TUyDqeZuFW	B	MJH66251901RAA31737261
...3	RCL30080501 20			B	MJH66251901RCL30080501
..2	EAD62887212 170		5JK1AhQJJ4Nj6XGgiMBEBB	B	AGL30243713 EAD62887212
S	EAD62887207 170			S	AGL30243713 EAD62887207
..2	MEG66672701180		xd_rGLURnJY6785X(choonjeong)	B	AGL30243713 MEG66672701
.1	AJV73149903 170	1.0	HZrBCDUwj6wpSYS0KaUm8X	B	LSEL6335F.ARS1497304901KHQ
..2	MJZ62162902 10	1.1	opcwxmaNed2rW760KaUllo	B	AJV73149903 MJZ62162902
...3	RAA33760007 10			B	MJZ62162902 RAA33760007
..2	MJZ62163003 20	1.0	i5IGEM7F4pT3diq0KaUm8X	B	AJV73149903 MJZ62163003
...3	RAA33760008 10			B	MJZ62163003 RAA33760008
.1	EAU63303803 180	1.2	j333hP03WdG8XPmc4YRdOr	B	LSEL6335F.ARS1497304901KHQ
..2	EAU62343004 10		q-bgEZKeBdl2ctuA33gBvX	B	EAU63303803 EAU62343004
..2	4810W1N060B20	1.2	phSSZ7eINLIHUB5VsWWtl-	B	EAU63303803 4810W1N060B
...3	RCL30078601 10		정도훈(dohhoonjeong)	B	4810W1N060BRCL30078601
..2	1NHA040001830		uVXZmoEQzHKgsflqXctXiX	B	EAU63303803 1NHA0400018
..2	3B72559A 40	1.3	nLv5D2lxO93NeKml8UpJ5K	B	EAU63303803 3B72559A
...3	9BAP0021D0010			B	3B72559A 9BAP0021D00
...3	RCL30079901 20			B	3B72559A RCL30079901
S	590081A002A 40			S	EAU63303803 590081A002A
..2	MGZ6360700250			B	EAU63303803 MGZ63607002
..2	FAD33778401 60		VEDZLMfAZd68sAC0KaUmGo	B	EAU63303803 FAD33778401

.1	EBF60663403 185		3S5IRgbPR5fuYn4H0abUjzn3.kim)	B	LSEL6335F.AR5HKK60634031EKHQ
.1	MDG62882901200	1.2	nzjOO4eiRfWGDJzXIIIRYpG	B	LSEL6335F.AR5MDG62882901EKHQ
..2	RAA33959301 10		QctigCgzKPtExKUR2igGZe	B	MDG62882901RAA33959301
..2	RCL30084301 20			B	MDG62882901RCL30084301
.1	MCK68473117210	1.1	4WMcFTEWahT-3VtdKL8brE	B	LSEL6335F.AR5MCK6847311EKHQ
..2	AGF79478703 10	1.0	y6iSrrCUPoZiKaPijkfpxz	B	MCK68473117AGF79478703
...3	RAB33372905 10	1.4		B	AGF79478703 RAB33372905
....4	RAB33416801 10	1.0	IN0FkrvXzp7Zy2i0KaUllv	B	RAB33372905 RAB33416801
....4	RAB35949601 20		정도훈(dohhoon.jeong)	B	RAB33372905 RAB35949601
S	RAB35949602 20			S	RAB33372905 RAB35949602
....4	RAB35329701 30		S2Y5i2keQWQ2894Kadlnhoon.jeong)	B	RAB33372905 RAB35329701
....4	RAB33370901 40		Ole8shNqylVb8v2084adlnhoon.jeong)	B	RAB33372905 RAB33370901
....4	RAB33371001 50		2nV3FJQQXxP9855084adlnhoon.jeong)	B	RAB33372905 RAB33371001
....4	RAB33371102 60		iGqRWbk0AwF834084adlnhoon.jeong)	B	RAB33372905 RAB33371102
S	RAB33371101 60			S	RAB33372905 RAB33371101
....4	RAB33370602 70		j3C9RCStQAn345584adlnhoon.jeong)	B	RAB33372905 RAB33370602
S	RAB33370601 70			S	RAB33372905 RAB33370601
....4	RAB33370701 80		tl0eJnUSr4xK9P80Kadlnhoon.jeong)	B	RAB33372905 RAB33370701
....4	RAB33490201 90		iGis1lefrllyZm4854134adlnhoon.jeong)	B	RAB33372905 RAB33490201
....4	RAB33371901 100		4rlGUUIC1ZUC3855084adlnhoon.jeong)	B	RAB33372905 RAB33371901
....4	RAB33371401 110		NbJnPtl3SZ2q834084adlnhoon.jeong)	B	RAB33372905 RAB33371401
....4	RAB33372001 120		0QWLEipk0GX8B455084adlnhoon.jeong)	B	RAB33372905 RAB33372001
....4	RAB35329802 130		jpXrLnBmfOON854784adlnhoon.jeong)	B	RAB33372905 RAB35329802
S	RAB35329801 130			S	RAB33372905 RAB35329801
....4	RAB33377701 140	1.0	u9gMWaaFT4oMwBE0KaUloW	B	RAB33372905 RAB33377701
....4	RAB33590401 150	1.0	h8Ea7MqLuhSpBr60KaUlos	B	RAB33372905 RAB33590401
....4	RAB37010601 160		vNgbxLgJx81Z854784adlnhoon.jeong)	B	RAB33372905 RAB37010601
....4	RAB33373104 170	1.0		B	RAB33372905 RAB33373104
.....5	RAB33416801 10	1.0	IN0FkrvXzp7Zy2i0KaUllv	B	RAB33373104 RAB33416801
.....5	RAB35949601 20		정도훈(dohhoon.jeong)	B	RAB33373104 RAB35949601
.....5	RAB33370901 30		Ole8shNqylVb8v2084adlnhoon.jeong)	B	RAB33373104 RAB33370901
.....5	RAB33371101 40		hsfaZJNYKcti854784adlnhoon.jeong)	B	RAB33373104 RAB33371101
.....5	RAB33416901 50	1.0	cgKRPg2W8bOJINK0KaUmOF	B	RAB33373104 RAB33416901
.....5	RAB33370601 60		if1ITu6RnYHUc854784adlnhoon.jeong)	B	RAB33373104 RAB33370601
.....5	RAB33370701 70		tl0eJnUSr4xK9P80Kadlnhoon.jeong)	B	RAB33373104 RAB33370701
.....5	RAB33490201 80		iGis1lefrllyZm4854134adlnhoon.jeong)	B	RAB33373104 RAB33490201
.....5	RAB33371901 90		4rlGUUIC1ZUC3855084adlnhoon.jeong)	B	RAB33373104 RAB33371901
....4	MAF63587801180		정도훈(dohhoon.jeong)	B	RAB33372905 MAF63587801

...3	MGA6278030120		ZsmONsgafwY6BxWXYLHwKx	B	AGF79478703 MGA62780301
...3	AGG7414570130	1.0	HSCXGRyQpmzXTBqzke8rV	B	AGF79478703 AGG74145701
....4	MFZ6359510110		bpHcik00YoGTFBI0KaUmVp	B	AGG74145701MFZ63595101
....4	MFZ6359520120		97WYse38gx3CPGLd5xcckCH	B	AGG74145701MFZ63595201
....4	MFZ6359530130		fTjUbjTC9TgHhj60KaUm7p	B	AGG74145701MFZ63595301
...3	MEZ6482290440		D92gTtMQvyqiKXBltGg8PX	B	AGF79478703 MEZ64822904
...3	MEZ6482290550		D92gTtMQvyqiKXBltGg8PX	B	AGF79478703 MEZ64822905
..2	MCK6847310930	1.0	k9De-tYoYEdYZJI-HEvcSB	B	MCK68473117MCK68473109
...3	RCL30081101 10		정도훈(dohhoon.jeong)	B	MCK68473109RCL30081101
S	MCK68473110210			S	LSEL6335F.ARS9116047311KHQ
.1	MAK61907202230	1.1	JosqFYbanvRp3aPsUPlxye	B	LSEL6335F.ARS9116047311KHQ
..2	RCL30095201 10			B	MAK61907202RCL30095201
.1	ABA75389604 250	1.0	P4jKjDJ9d08-RPJ-Mpibb1	B	LSEL6335F.ARS9116047311KHQ
..2	MAZ6236520310		uOpLrKqG69sXUVp_TTdWON	B	ABA75389604 MAZ62365203
..2	MAZ6472600320		heOQpzrfr7lqqoq0KaUmYL	B	ABA75389604 MAZ64726003
..2	FAC30139502 30		Z2VmtiywwscAkqAhv1zB3X	B	ABA75389604 FAC30139502
S	ABA75389602 250			S	LSEL6335F.ARS9116047311KHQ
.1	ABQ30097002260	2.0	mxHtbqbUI770MVtxC835BE	B	LSEL6335F.ARS9116047311KHQ
..2	ADJ74172315 10	1.1	KKQ2sUVT1Kxl5gcoz9X-e4	B	ABQ30097002ADJ74172315
...3	MBN6384501710	1.1	kud8aB7OF1HwPw42J6pJQs	B	ADJ74172315 MBN63845017
....4	RAA33956557 10		v7L9EuqTWZdlGblfvfA_G4	B	MBN63845017RAA33956557
...3	MBN6384510420	1.1	j5AThtHraiEi5LvumB6fUI	B	ADJ74172315 MBN63845104
....4	RAA31737297 10		tER-xr9NhcMIM1oiQDyhNx	B	MBN63845104RAA31737297
S	ADJ74172309 10			S	ABQ30097002ADJ74172309
..2	MEV6589761420		ZsUGVC2CgLP_ZTenuLqNqV	B	ABQ30097002MEV65897614
..2	MAZ6354810130	1.2	Rz0rSARplkWEKLQ0KaUmGz	B	ABQ30097002MAZ63548101
...3	RAA34298101 10			B	MAZ63548101RAA34298101
...3	RCL30080501 20			B	MAZ63548101RCL30080501
..2	6322W2A001S40			B	ABQ300970026322W2A001S
..2	4B72510F 50		yM4D5hNCMfyyKWuZ9hw206	B	ABQ300970024B72510F
..2	1TTL0402418 60		XhHe7pwalRF_3t-IVwAcYc	B	ABQ300970021TTL0402418
..2	MEG6667270170		xd_rGLURnJY6735Xy(dohhoon.jeong)	B	ABQ30097002MEG66672701
.1	MJH66325501285	1.2	QHD370q3nVxEf6O0KaUmXt	B	LSEL6335F.ARS9116047311KHQ
..2	RAA33958302 10			B	MJH66325501RAA33958302
..2	RCL30080101 20			B	MJH66325501RCL30080101
.1	ADP30238101 290	1.0	k0BJeheBQYNrbcmPuNvaHB	B	LSEL6335F.ARS9116047311KHQ
..2	ADP74013401 10			B	ADP30238101 ADP74013401
..2	AJV73149801 20	1.3	hQdUsZvlt4cXsiu0KaUm7E	B	ADP30238101 AJV73149801

...3	MJZ62163101 10	1.4	iCzCnAeC8lh8ll20KaUm7E	B	AJV73149801 MJZ62163101
....4	RAA34016901 10		sf3-AMJSGLiVIClOUvINyj	B	MJZ62163101 RAA34016901
....4	RCL30080501 20			B	MJZ62163101 RCL30080501
...3	MJZ62163201 20	1.4	R0iyLYVxxnoRxFokkqfpgA	B	AJV73149801 MJZ62163201
....4	RAA34017001 10		mT0xwRsuT3XY5FYMb-dkoi	B	MJZ62163201 RAA34017001
....4	RCL30080501 20			B	MJZ62163201 RCL30080501
..2	MCQ670844160		miQZ8XkZ0n5clUZKB_g5GA	B	ADP30238101 MCQ67084416
..2	MCK7152610140		iD40xTzc7gsafC40KaUlJv	B	ADP30238101 MCK71526101
..2	1TTL0402418 50		XhHe7pwalRF_3t-IVwAcYc	B	ADP30238101 1TTL0402418
.1	ADG73691108310	1.1	mAJDrQ_aZt-dNrhsXd8QN2	B	LSEL6335F.ARSADG73691108310KHQ
..2	AGU3002261110	1.1	TMHUBxjAmsW8db3ijijPeL	B	ADG73691108AGU30022611
...3	MGJ6700480710	1.0	b8FZFhknef-YiyUrofXk_B	B	AGU30022611MGJ67004807
....4	RAA31737281 10		ptH4hmPDp8ngLiRl3uQoD	B	MGJ67004807RAA31737281
...3	4778W1N001A20	1.2		B	AGU300226114778W1N001A
....4	RAA35457601 10		최효은(hyoeun.choi)	B	4778W1N001ARA35457601
..2	AGU3002261220	1.1	dsf3WsjTiAmqHaldSsFH0T	B	ADG73691108AGU30022612
...3	MGJ6700480710	1.0	b8FZFhknef-YiyUrofXk_B	B	AGU30022612MGJ67004807
....4	RAA31737281 10		ptH4hmPDp8ngLiRl3uQoD	B	MGJ67004807RAA31737281
...3	4778W1N001A20	1.2		B	AGU300226124778W1N001A
....4	RAA35457601 10		최효은(hyoeun.choi)	B	4778W1N001ARA35457601
..2	MDP6244700430		1eoBtzbPpiWhXxQ0KaUlqL	B	ADG73691108MDP62447004
..2	MGJ6754120140	1.2	AZBdv3ldFfdHzT4KDBJKzl	B	ADG73691108MGJ67541201
...3	RAA3315570410		fQDx93fre9OqjNDwE79###(jordan.diaz)	B	MGJ67541201RAA33155704
..2	MAZ6776850150	1.2	xkCqqHkG8SerruhtKuEh0W	B	ADG73691108MAZ67768501
...3	RAA3315570410		fQDx93fre9OqjNDwE79###(jordan.diaz)	B	MAZ67768501RAA33155704
..2	MAZ6776910160	1.2	faL4klyR72y6JkgdeUzSP4	B	ADG73691108MAZ67769101
...3	RAA3315570410		fQDx93fre9OqjNDwE79###(jordan.diaz)	B	MAZ67769101RAA33155704
..2	MEV6776580570	1.0	r5fAXyYVPvuTVhMK9wQkZm	B	ADG73691108MEV67765805
...3	RAA33959179 10			B	MEV67765805RAA33959179
S	RAA33959184 10			S	MEV67765805RAA33959184
..2	MHS6202230180	1.1	NY198Peok8LK7nc0KaUmAA	B	ADG73691108MHS62022301
...3	RCL30094901 10			B	MHS62022301RCL30094901
..2	MGC661803180	1.0	Kv-xFR7Yx4Vfr5CjSOTg0J	B	ADG73691108MGC66180318
...3	MGC6618031710	1.1	Kv-xFR7Yx4Vfr5CjSOTg0J	B	MGC66180318MGC66180317
....4	RAA33956313 10		Po3GwzxXyzyG2HA0KaUm4j	B	MGC66180317RAA33956313
....4	RCL30084001 20			B	MGC66180317RCL30084001
...3	1VZZA90001A20		2P4urTdnjTJRQ0HI85JKbY	B	MGC661803181VZZA90001A
..2	MFZ63953008100		smzabuBldYk3yilXy029wK	B	ADG73691108MFZ63953008

..2	MCX62743102110	1.0	n7edKfZ2VqL-OYJktLobFB	B	ADG73691108MCX62743102
...3	RAA33155706 10		CCRDqaJV7koE1ttNtOciTF	B	MCX62743102RAA33155706
..2	MHS62022201120	1.1	wyw8UG60cX7ioXQ0KaUmpy	B	ADG73691108MHS62022201
...3	RCL30094901 10			B	MHS62022201RCL30094901
..2	MDQ66517504 130	1.1	y-NvF60AEuKva58y8uL6cu	B	ADG73691108MDQ66517504
...3	RAA31737280 10		EHShd4aAvnVrPpOr7thJdd	B	MDQ66517504RAA31737280
...3	RCL30078201 20			B	MDQ66517504RCL30078201
..2	4980W1N013A 140	1.0	cld69vPD-5T6WgaJ70nQep	B	ADG736911084980W1N013A
...3	8PBT0110001 30			B	4980W1N013A8PBT0110001
..2	1TTL0402418 150		XhHe7pwalRF_3t-IVwAcYc	B	ADG736911081TTL0402418
Q	1TTL0402418 150		XhHe7pwalRF_3t-IVwAcYc	Q	ADG736911081TTL0402418
Q	1TTL0402418 150		XhHe7pwalRF_3t-IVwAcYc	Q	ADG736911081TTL0402418
Q	1TTL0402418 150		XhHe7pwalRF_3t-IVwAcYc	Q	ADG736911081TTL0402418
Q	1TTL0402418 150		XhHe7pwalRF_3t-IVwAcYc	Q	ADG736911081TTL0402418
Q	1TTL0402418 150		XhHe7pwalRF_3t-IVwAcYc	Q	ADG736911081TTL0402418
..2	1TTL0402416 160		TAZNml3DLp_dHtPRwHuVc8	B	ADG736911081TTL0402416
..2	1TTL0402818 170		0Oc9F3DT1VFy0dt36F2vwO	B	ADG736911081TTL0402818
..2	FAB31821702 180			B	ADG73691108FAB31821702
S	1SZZW5N001E 180			S	ADG736911081SZZW5N001E
S	ADG73691107310			S	LSEL6335F.ARG73691107310EKHQ
.1	MAZ64788501320	1.2		B	LSEL6335F.ARG73691107310EKHQ
..2	RAA34077101 10		a3k3QBGY5h5jkbVl2NBbka	B	MAZ64788501RAA34077101
..2	RCL30079001 20			B	MAZ64788501RCL30079001
.1	MEA66346502345	1.1	EFcmT_DWsHBlq12JNZ6AUE	B	LSEL6335F.ARG73691107310EKHQ
..2	RAA31737260 10		qT9Ndk5LiOQgAMFMDmV6ZQUEZ(samaBtha.v...		MEA66346502RAA31737260
..2	RCL30080501 20			B	MEA66346502RCL30080501
.1	AJJ76418406 350	1.0	IX8FIE2XP9jir5s0KaUmHF	B	LSEL6335F.ARG73691107310EKHQ
..2	MJH66093801 10	1.3	sqtW1Zq8asct5VG35gR7KJ	B	AJJ76418406 MJH66093801
...3	8PPC8730002 10			B	MJH660938018PPC8730002
..2	EBR30162712 20			B	AJJ76418406 EBR30162712
S	AJJ76418402 350			S	LSEL6335F.ARG73691107310EKHQ
.1	AGL30062501 370	1.2	fpW4tjpylklT9l_mkYBl7	B	LSEL6335F.ARG73691107310EKHQ
..2	MGC62644032 10	1.0	U28IOaSH-m41w-51Vjgvb3	B	AGL30062501 MGC62644032
...3	RAA33154906 10		UyMTqWwdtCwMhcLXF0oWkx	B	MGC62644032RAA33154906
..2	MFZ67262501 20		o2DnfZTj1FhJwGoOwJ3ndw	B	AGL30062501 MFZ67262501
.1	AGL30062502 375	1.2	mO7Bx-S5O2eTd-80pexoCc	B	LSEL6335F.ARG73691107310EKHQ
..2	MGC62644033 10	1.0	67CxbFv8t5nKi-FgsiGNsY	B	AGL30062502 MGC62644033
...3	RAA33154906 10		UyMTqWwdtCwMhcLXF0oWkx	B	MGC62644033RAA33154906

[illegible]

[illegible]

....4	0RH4701C42250	B	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
Q	0RH4701C42250	Q	EBR38163503 0RH4701C422
....4	0TR150409BF 60	B	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
Q	0TR150409BF 60	Q	EBR38163503 0TR150409BF
....4	0TR166608AA 70	B	EBR38163503 0TR166608AA
Q	0TR166608AA 70	Q	EBR38163503 0TR166608AA
....4	EAH61438102 80	B	EBR38163503 EAH61438102

Q	EAH61438102 80		Q	EBR38163503 EAH61438102
Q	EAH61438102 80		Q	EBR38163503 EAH61438102
Q	EAH61438102 80		Q	EBR38163503 EAH61438102
...4	EAH63473601 90	ANDREA CARDENAS(Andrea Cardenas)	B	EBR38163503 EAH63473601
Q	EAH63473601 90	ANDREA CARDENAS(Andrea Cardenas)	Q	EBR38163503 EAH63473601
Q	EAH63473601 90	ANDREA CARDENAS(Andrea Cardenas)	Q	EBR38163503 EAH63473601
...4	EAN63688101 100	hQIMsSWpvpElcWm0KaUmNH	B	EBR38163503 EAN63688101
Q	EAN63688101 100	hQIMsSWpvpElcWm0KaUmNH	Q	EBR38163503 EAN63688101
...4	6630AQ9113E 110		B	EBR38163503 6630AQ9113E
Q	6630AQ9113E 110		Q	EBR38163503 6630AQ9113E
...4	OCE105EKK38 120		B	EBR38163503 OCE105EKK38
Q	OCE105EKK38 120		Q	EBR38163503 OCE105EKK38
Q	OCE105EKK38 120		Q	EBR38163503 OCE105EKK38
...4	ORH1002C422130		B	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
Q	ORH1002C422130		Q	EBR38163503 ORH1002C422
...4	OISTLKE003A 140		B	EBR38163503 OISTLKE003A
Q	OISTLKE003A 140		Q	EBR38163503 OISTLKE003A
...4	OILNRKE018A 150		B	EBR38163503 OILNRKE018A
Q	OILNRKE018A 150		Q	EBR38163503 OILNRKE018A
...4	EBC65441803 160	ANDREA CARDENAS(Andrea Cardenas)	B	EBR38163503 EBC65441803
Q	EBC65441803 160	ANDREA CARDENAS(Andrea Cardenas)	Q	EBR38163503 EBC65441803
Q	EBC65441803 160	ANDREA CARDENAS(Andrea Cardenas)	Q	EBR38163503 EBC65441803
...4	OCE477EK618 170		B	EBR38163503 OCE477EK618
Q	OCE477EK618 170		Q	EBR38163503 OCE477EK618
...4	EAB62848203 180		B	EBR38163503 EAB62848203
Q	EAB62848203 180		Q	EBR38163503 EAB62848203
...4	ORH5600C622190		B	EBR38163503 ORH5600C622
Q	ORH5600C622190		Q	EBR38163503 ORH5600C622

[illegible]

[illegible]

Q	EAE63065701	300		Q	EBR38163503 EAE63065701
S	OCK104BH64B	300		S	EBR38163503 OCK104BH64B
....4	OIKE358000C	310		B	EBR38163503 OIKE358000C
Q	OIKE358000C	310		Q	EBR38163503 OIKE358000C
....4	EAE63662201	320		B	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAE63662201	320		Q	EBR38163503 EAE63662201
Q	EAG64310003	330	ANDREA CARDENAS(Andrea Cardenas)	Q	EBR38163503 EAG64310003
Q	EAG64310003	330	ANDREA CARDENAS(Andrea Cardenas)	Q	EBR38163503 EAG64310003
....4	EAE63071109	340		B	EBR38163503 EAE63071109
Q	EAE63071109	340		Q	EBR38163503 EAE63071109
....4	OILI817000W	350		B	EBR38163503 OILI817000W
Q	OILI817000W	350		Q	EBR38163503 OILI817000W
Q	OILI817000W	350		Q	EBR38163503 OILI817000W
....4	ORH1004C622	360		B	EBR38163503 ORH1004C622
Q	ORH1004C622	360		Q	EBR38163503 ORH1004C622
....4	EBC61056801	370		B	EBR38163503 EBC61056801
Q	EBC61056801	370		Q	EBR38163503 EBC61056801

[illegible]

Q	0RH1000C422430			Q	EBR38163503 0RH1000C422
Q	0RH1000C422430			Q	EBR38163503 0RH1000C422
Q	0RH1000C422430			Q	EBR38163503 0RH1000C422
Q	0RH1000C422430			Q	EBR38163503 0RH1000C422
Q	0RH1000C422430			Q	EBR38163503 0RH1000C422
....4	0CE475EKK10 440			B	EBR38163503 0CE475EKK10
Q	0CE475EKK10 440			Q	EBR38163503 0CE475EKK10
....4	EAX69920101 450	A	oBYgxG81ZCHsgy00KaUnM8	B	EBR38163503 EAX69920101
....4	0TR387509AB 460			B	EBR38163503 0TR387509AB
Q	0TR387509AB 460			Q	EBR38163503 0TR387509AB
Q	0TR387509AB 460			Q	EBR38163503 0TR387509AB
Q	0TR387509AB 460			Q	EBR38163503 0TR387509AB
Q	0TR387509AB 460			Q	EBR38163503 0TR387509AB
Q	0TR387509AB 460			Q	EBR38163503 0TR387509AB
Q	0TR387509AB 460			Q	EBR38163503 0TR387509AB
Q	0TR387509AB 460			Q	EBR38163503 0TR387509AB
....4	EAE64708301 470			B	EBR38163503 EAE64708301
Q	EAE64708301 470			Q	EBR38163503 EAE64708301
Q	EAE64708301 470			Q	EBR38163503 EAE64708301
....4	6630W5V012F480		ANDREA CARDENAS(andreaCard...		EBR38163503 6630W5V012F
Q	6630W5V012F480		ANDREA CARDENAS(andreaCard...		EBR38163503 6630W5V012F
....4	EAH61515501 490		I5Gms5ndsv0LFW0KAVFns1.dave)	B	EBR38163503 EAH61515501
Q	EAH61515501 490		I5Gms5ndsv0LFW0KAVFns1.dave)	Q	EBR38163503 EAH61515501
Q	EAH61515501 490		I5Gms5ndsv0LFW0KAVFns1.dave)	Q	EBR38163503 EAH61515501
Q	EAH61515501 490		I5Gms5ndsv0LFW0KAVFns1.dave)	Q	EBR38163503 EAH61515501
Q	EAH61515501 490		I5Gms5ndsv0LFW0KAVFns1.dave)	Q	EBR38163503 EAH61515501
Q	EAH61515501 490		I5Gms5ndsv0LFW0KAVFns1.dave)	Q	EBR38163503 EAH61515501
Q	EAH61515501 490		I5Gms5ndsv0LFW0KAVFns1.dave)	Q	EBR38163503 EAH61515501
Q	EAH61515501 490		I5Gms5ndsv0LFW0KAVFns1.dave)	Q	EBR38163503 EAH61515501
Q	EAH61515501 490		I5Gms5ndsv0LFW0KAVFns1.dave)	Q	EBR38163503 EAH61515501
....4	6212A90001L 500			B	EBR38163503 6212A90001L
Q	6212A90001L 500			Q	EBR38163503 6212A90001L
....4	6630A90002K 510			B	EBR38163503 6630A90002K
Q	6630A90002K 510			Q	EBR38163503 6630A90002K
....4	0RH1001C422520			B	EBR38163503 0RH1001C422
Q	0RH1001C422520			Q	EBR38163503 0RH1001C422
Q	0RH1001C422520			Q	EBR38163503 0RH1001C422
Q	0RH1001C422520			Q	EBR38163503 0RH1001C422
Q	0RH1001C422520			Q	EBR38163503 0RH1001C422

[illegible]

Q	0RH0102C622560			Q	EBR38163503 0RH0102C622
...4	EAN66309901 570			B	EBR38163503 EAN66309901
Q	EAN66309901 570			Q	EBR38163503 EAN66309901
...4	EAG64230201 580		ANDREA CARDENAS(Andrea Cardenas)	B	EBR38163503 EAG64230201
Q	EAG64230201 580		ANDREA CARDENAS(Andrea Cardenas)	Q	EBR38163503 EAG64230201
Q	EAG64230201 580		ANDREA CARDENAS(Andrea Cardenas)	Q	EBR38163503 EAG64230201
...4	0RJ1000H680 590			B	EBR38163503 0RJ1000H680
Q	0RJ1000H680 590			Q	EBR38163503 0RJ1000H680
Q	0RJ1000H680 590			Q	EBR38163503 0RJ1000H680
...4	EBC65441801 600		ANDREA CARDENAS(Andrea Cardenas)	B	EBR38163503 EBC65441801
Q	EBC65441801 600		ANDREA CARDENAS(Andrea Cardenas)	Q	EBR38163503 EBC65441801
...4	SAA42472301 610	1.0		B	EBR38163503 SAA42472301
...3	EBR32418503 60	1.0	iR1dLUo1E65l3m1ipu3CZS	B	AJJ76597516 EBR32418503
...4	SAA42322103 10		nA2YCMF80UrZhceOC6MAel	B	EBR32418503 SAA42322103
...3	1TPL0402418 70		wMMHmdjg7drTBWS0KaUmQh	B	AJJ76597516 1TPL0402418
Q	1TPL0402418 70		wMMHmdjg7drTBWS0KaUmQh	Q	AJJ76597516 1TPL0402418
...3	7250PT0066N 80		S81kgTXo600OQp3eobHhZv	B	AJJ76597516 7250PT0066N
...3	MEZ6889190290		ClTWqNurAbSKZDREAUCARDENAS(Andrea Cardenas)	B	AJJ76597516 MEZ68891902
..2	MGC6637170820	1.1	SdjMfgEXmJ0wHiK0KaUmer	B	ACM76195004MGC66371708
...3	MGC6637170410	1.2	795k5e7YQ05e72e0KaUmdy	B	MGC66371708MGC66371704
...4	RSH31009910 10		lAqH4ifKgAfB8Nc0KaUmNa	B	MGC66371704RSH31009910
...3	AKF75718904 20		qwMpmeHokb0xsf3xg5ln1	B	MGC66371708AKF75718904
...3	1VZZA90001A30		2P4urTdnjTJRQ0HI85JKbY	B	MGC663717081VZZA90001A
..2	MCK6202800330		lFHaYjsKullGzsO0KaUmIP	B	ACM76195004MCK62028003
..2	EAQ6065830340		guACVUcTaLIS8jg0KaUmJJ	B	ACM76195004EAQ60658303
..2	EBF62174906 50	1.0	w8pCGiRZYT9qej_hRvAQJ6	B	ACM76195004EBF62174906
...3	MHJ6587820110	1.0	eZUVV19ZoCPyf680KaUmV8	B	EBF62174906 MHJ65878201
...3	MCK7186640120	1.0	xmyoaH0xpsjKAXk0KaUloM	B	EBF62174906 MCK71866401
..2	EBF62174907 60	1.0	w8pCGiRZYT9qej_hRvAQJ6	B	ACM76195004EBF62174907
...3	MHJ6587820110	1.0	eZUVV19ZoCPyf680KaUmV8	B	EBF62174907 MHJ65878201
...3	MCK7186640120	1.0	xmyoaH0xpsjKAXk0KaUloM	B	EBF62174907 MCK71866401
..2	EBF62174908 70	1.0	w8pCGiRZYT9qej_hRvAQJ6	B	ACM76195004EBF62174908
...3	MHJ6587820110	1.0	eZUVV19ZoCPyf680KaUmV8	B	EBF62174908 MHJ65878201
...3	MCK7186640120	1.0	xmyoaH0xpsjKAXk0KaUloM	B	EBF62174908 MCK71866401
..2	EBF63054503 80		5sKC6uRz8XzQH-HHfs6ncu	B	ACM76195004EBF63054503
..2	EAD63748816 90		XFOM1-hLVElGa4CNup0CTj	B	ACM76195004EAD63748816
..2	FAB30455601 110		lbaHxmjVeSgKca00KaUm96	B	ACM76195004FAB30455601
Q	FAB30455601 110		lbaHxmjVeSgKca00KaUm96	Q	ACM76195004FAB30455601

..2	1SZZW2A004E120		RnAXuaknArBt_ywVaxncol	B	ACM761950041SZZW2A004E
Q	1SZZW2A004E120		RnAXuaknArBt_ywVaxncol	Q	ACM761950041SZZW2A004E
..2	3880W1A015D130		78Q03YZQefCQYIb_jdQACq	B	ACM761950043880W1A015D
Q	3880W1A015D130		78Q03YZQefCQYIb_jdQACq	Q	ACM761950043880W1A015D
..2	MEZ57157120150		jwyR8tt0Fu_V-nUFdBpqFe	B	ACM76195004MEZ57157120
..2	MCQ67084422160		miQZ8XkZ0n5clUZKB_g5GA	B	ACM76195004MCQ67084422
S	4B73438L 160			S	ACM761950044B73438L
..2	MEZ68892402170		46eo-Y6nC5SloDWl3wa6p8	B	ACM76195004MEZ68892402
..2	MEZ68891928180		npX7Ut2Pdizo82yZn2Vmoon.jeong)	B	ACM76195004MEZ68891928
.1	EAD65883501 402		4rlxjKES7fwhEtVlryaPh	B	LSEL6335F.ARS9AD65883501KHQ
.1	AGU74969415405	2.0	5EogXFRUcVQ5B0C0KaUlsH	B	LSEL6335F.ARS9AGU74969415KHQ
..2	AGU7504901310	2.1	FXrowqYqFNaDHFjczU0Pay	B	AGU74969415AGU75049013
...3	ACQ3038332530	1.0	1Upjy-SC4-Zh2RrD4_rMrO	B	AGU75049013ACQ30383325
....4	MGJ6720570110	1.5	7M8c7n2DUfodZhRSg3a4IH	B	ACQ30383325MGJ67205701
.....5	RSH31009901 10			B	MGJ67205701RSH31009901
....4	MGJ6720540120		V3RfhbQJz7eLWCm0KaUm6b	B	ACQ30383325MGJ67205401
....4	MGJ6720540230		VRcWetmlbjgdxiq0KaUm6b	B	ACQ30383325MGJ67205402
....4	1VZZA90001A40		2P4urTdnjTJRQ0HI85JKbY	B	ACQ303833251VZZA90001A
....4	RAB36916002 50		Lp_qeUXIdMqBQt6gRg58m4	B	ACQ30383325RAB36916002
....4	RAB36916004 60		Lp_qeUXIdMqBQt6gRg58m4	B	ACQ30383325RAB36916004
...3	MKC6533966150	1.0	0QKGEgyoPCyhZ0qFqwMwJR	B	AGU75049013MKC65339661
....4	AKF74335518 10		UrD9CEktuL2wjvQFG76mJE	B	MKC65339661AKF74335518
S	MKC6533963750			S	AGU75049013MKC65339637
S	MKC6533964650			S	AGU75049013MKC65339646
S	MKC6533962750			S	AGU75049013MKC65339627
...3	RAC3269730460			B	AGU75049013RAC32697304
...3	RAC35977501 70	1.0	XJjxW8uUnXoU9aa0KaUmQg	B	AGU75049013RAC35977501
..2	MEE6238520620			B	AGU74969415MEE62385206
S	MEE62385201 20			S	AGU74969415MEE62385201
..2	MEE6270490330			B	AGU74969415MEE62704903
S	MEE62704901 30			S	AGU74969415MEE62704901
..2	MEE6238500140		7F7VD0CkU8gFtK0DWHdX8P	B	AGU74969415MEE62385001
..2	AEG33897013 50		ViKGcTzjdFkp6NCYQC61O-	B	AGU74969415AEG33897013
..2	MAZ6331080160	1.3	CH-mXJvap20vVQXUSTM54A	B	AGU74969415MAZ63310801
...3	RIR30003301 10			B	MAZ63310801RIR30003301
..2	EAD62705314 70		fSsqBF3N8mi91E0KaUmZm	B	AGU74969415EAD62705314
..2	1TTL0402418 90		XhHe7pwalRF_3t-IVwAcYc	B	AGU749694151TTL0402418
Q	1TTL0402418 90		XhHe7pwalRF_3t-IVwAcYc	Q	AGU749694151TTL0402418

Q	1TTL0402418 90		XhHe7pwalRF_3t-IVwAcYc	Q	AGU749694151TTL0402418
Q	1TTL0402418 90		XhHe7pwalRF_3t-IVwAcYc	Q	AGU749694151TTL0402418
..2	4980W1N014A400	1.0	bLki819fd69TcDCEDPSCw-	B	AGU749694154980W1N014A
...3	8PBT0110001 20			B	4980W1N014A8PBT0110001
..2	3920W1N014A410		MPuIJ32FJgED0ee0KaUmUg	B	AGU749694153920W1N014A
..2	MAZ64865801120	1.2	CqZODjtin3gW6iG0KaUmOr	B	AGU74969415MAZ64865801
...3	RAA33956526 10			B	MAZ64865801RAA33956526
...3	RCL30080501 20			B	MAZ64865801RCL30080501
..2	1TTL0403118 130		qeZLvCTHwMW1IJ2Kn0zh9G	B	AGU749694151TTL0403118
..2	MAZ40417403140		BoTFfgk6C242WhJVqlm3De	B	AGU74969415MAZ40417403
.1	AEZ75853758 406	1.1	lDmG66r9ruW5y3E0KaUmTE	B	LSEL6335F.ARS.AEZ75853758AEKHQ
..2	MEY6527475610	1.0	u9fjdEosjvxTjUyYqoVpj_	B	AEZ75853758 MEY65274756
...3	RAA34560801 10			B	MEY65274756RAA34560801
...3	AKF75594446 20			B	MEY65274756AKF75594446
..2	MEY6391410120	1.0	rdQ2XzO2PNgrCJk0KaUmZs	B	AEZ75853758 MEY63914101
...3	RCL30095001 10			B	MEY63914101RCL30095001
..2	MEY6546190130	1.1	wOp0A2EdEowXppgR08LpNe	B	AEZ75853758 MEY65461901
...3	RAA34560801 10			B	MEY65461901RAA34560801
..2	1SZZW2E001D40		WFHGmxGg0Nf1Cd60KaUmOG	B	AEZ75853758 1SZZW2E001D
..2	MHY6185390350	1.0	peguTp0EtEO2B4m0Ks0mHfJc0ng)	B	AEZ75853758 MHY61853903
...3	RCL30087501 10			B	MHY61853903RCL30087501
..2	7525W5S000160		wTuBRVr5FGDm0W00KaUmB8	B	AEZ75853758 7525W5S0001
S	AEZ75853737 406			S	LSEL6335F.ARS.AEZ75853737AEKHQ
.1	AEZ75853757 406	1.2	kpbP8oUiFiTnWXA0KaUmTE	B	LSEL6335F.ARS.AEZ75853757AEKHQ
..2	MEY6527475510	1.0	-xsPgTQ-c5uEqxNdlhWAeU	B	AEZ75853757 MEY65274755
...3	RAA34560801 10			B	MEY65274755RAA34560801
...3	AKF75594445 20			B	MEY65274755AKF75594445
..2	MEY6391410320		s1atVHKU1zj9dpo0KaUmZs	B	AEZ75853757 MEY63914103
..2	MEY6546190130	1.1	wOp0A2EdEowXppgR08LpNe	B	AEZ75853757 MEY65461901
...3	RAA34560801 10			B	MEY65461901RAA34560801
..2	1SZZW2E001D40		WFHGmxGg0Nf1Cd60KaUmOG	B	AEZ75853757 1SZZW2E001D
..2	MHY6185390350	1.0	peguTp0EtEO2B4m0Ks0mHfJc0ng)	B	AEZ75853757 MHY61853903
...3	RCL30087501 10			B	MHY61853903RCL30087501
..2	7525W5S000160		wTuBRVr5FGDm0W00KaUmB8	B	AEZ75853757 7525W5S0001
S	AEZ75853736 406			S	LSEL6335F.ARS.AEZ75853736AEKHQ
.1	AEZ75853759 406	1.2	lBx73PDbUWYOPZIOKaUmTE	B	LSEL6335F.ARS.AEZ75853759AEKHQ
..2	MEY6527475710	1.0	9rPlrEAluQy6RvL0IPYFgc	B	AEZ75853759 MEY65274757
...3	RAA34560801 10			B	MEY65274757RAA34560801

...3	AKF75594447 20			B	MEY65274757AKF75594447
..2	MEY6391410420	1.0	sPlkSa6veblSSLS0KaUmZs	B	AEZ75853759 MEY63914104
...3	RCL30095001 10			B	MEY63914104RCL30095001
..2	MEY6546190130	1.1	wOp0A2EdEowXppgR08LpNe	B	AEZ75853759 MEY65461901
...3	RAA34560801 10			B	MEY65461901RAA34560801
..2	1SZZW2E001D40		WFHGmxGg0Nf1Cd60KaUmOG	B	AEZ75853759 1SZZW2E001D
..2	MHY6185390350	1.0	peguTp0EtEO2B4m0Ks0dmfEeong)	B	AEZ75853759 MHY61853903
...3	RCL30087501 10			B	MHY61853903RCL30087501
..2	7525W5S000160		wTuBRVr5FGDm0W00KaUmB8	B	AEZ75853759 7525W5S0001
S	AEZ75853738 406			S	LSEL6335F.ARS.AEZ75853738KHQ
.1	AEZ75853756 406	1.2	kRQYBW8GcgRV5160KaUmTE	B	LSEL6335F.ARS.AEZ75853756KHQ
..2	MEY6527475410	1.0	6Ealt1oXpCJGDb1spo3okO	B	AEZ75853756 MEY65274754
...3	RAA34560801 10			B	MEY65274754RAA34560801
...3	AKF75594444 20			B	MEY65274754AKF75594444
..2	MEY6391410520	1.0	snwbPsTNHDnkWrw0KaUmZs	B	AEZ75853756 MEY63914105
...3	RCL30095001 10			B	MEY63914105RCL30095001
..2	MEY6546190130	1.1	wOp0A2EdEowXppgR08LpNe	B	AEZ75853756 MEY65461901
...3	RAA34560801 10			B	MEY65461901RAA34560801
..2	1SZZW2E001D40		WFHGmxGg0Nf1Cd60KaUmOG	B	AEZ75853756 1SZZW2E001D
..2	MHY6185390350	1.0	peguTp0EtEO2B4m0Ks0dmfEeong)	B	AEZ75853756 MHY61853903
...3	RCL30087501 10			B	MHY61853903RCL30087501
..2	7525W5S000160		wTuBRVr5FGDm0W00KaUmB8	B	AEZ75853756 7525W5S0001
S	AEZ75853735 406			S	LSEL6335F.ARS.AEZ75853735KHQ
.1	ADC30055701407	1.5		B	LSEL6335F.ARS.ADC30055701KHQ
..2	AEH76198001 10	1.0	Nfn1nFhLlf3qHjglj4Fyvk	B	ADC30055701AEH76198001
...3	MEK6446660210		KdC3dH8PYWZQ7rl9ifaLDi	B	AEH76198001 MEK64466602
...3	MEK6519710120		5xWKdXpcQEvaGiDpaOJHqm	B	AEH76198001 MEK65197101
...3	MFC6402950330		mgXx70GOxZJI-rhHM2YGpx	B	AEH76198001 MFC64029503
...3	MFG6468460140		Z8lpZ4OHQQYIsGsRpPFraj	B	AEH76198001 MFG64684601
...3	MAK6541240150	1.1	nXPMFCaoav_gdXDIsJ04Z5	B	AEH76198001 MAK65412401
....4	RCL30076101 10			B	MAK65412401RCL30076101
..2	MCK6847320120	1.3	_tBmODYIZ4NBbrCbJmMvyP	B	ADC30055701MCK68473201
...3	RAA33956505 10			B	MCK68473201RAA33956505
...3	RCL30080101 20			B	MCK68473201RCL30080101
..2	4890W1N009G30		2F3A1YRB7igrDI80KaUmlD	B	ADC300557014890W1N009G
..2	MAZ6456940140	1.2	dyoN1KC49HEJgmGm9qhpxG	B	ADC30055701MAZ64569401
...3	RAA33958301 10		tiN8pd7TJcjbjs2kiQXzbQ	B	MAZ64569401RAA33958301
...3	RCL30080101 20			B	MAZ64569401RCL30080101

..2	MEV6511550850		mWVG6ArVteYxwzQ0KaUmPS	B	ADC30055701MEV65115508
..2	MEV6511550960		mug73TDxWGbGOVU0KaUmPS	B	ADC30055701MEV65115509
..2	MEV6511551070		nlqy0IaP8sdYq1Y0KaUmPS	B	ADC30055701MEV65115510
..2	3300W1N003N0		pR6wacFdltFe5MO0KaUlPM	B	ADC300557013300W1N003N
..2	MDQ641769080	1.2	W9k8AnZRkH9gdSOKfJbyO1	B	ADC30055701MDQ64176908
...3	MDQ641769070	1.1	W9k8AnZRkH9gdSOKfJbyO1	B	MDQ64176908MDQ64176907
....4	RAA33996702 10		Ro5y9AFNRyehRzs0KaUmBX	B	MDQ64176907RAA33996702
....4	RCL30081101 20		정도훈(dohhoon.jeong)	B	MDQ64176907RCL30081101
...3	RAB33372905 20	1.4		B	MDQ64176908RAB33372905
....4	RAB33416801 10	1.0	IN0FkrvXzp7Zy2i0KaUllv	B	RAB33372905 RAB33416801
....4	RAB35949601 20		정도훈(dohhoon.jeong)	B	RAB33372905 RAB35949601
S	RAB35949602 20			S	RAB33372905 RAB35949602
....4	RAB35329701 30		S2Y5i2keQWQ28K9P(dohhoon.jeong)	B	RAB33372905 RAB35329701
....4	RAB33370901 40		Ole8shNqyLvob8Z0KaUmPS	B	RAB33372905 RAB33370901
....4	RAB33371001 50		2nV3FJQQXxP9b5C0KaUmPS	B	RAB33372905 RAB33371001
....4	RAB33371102 60		iGqRWbk0AwF8A0KaUmPS	B	RAB33372905 RAB33371102
S	RAB33371101 60			S	RAB33372905 RAB33371101
....4	RAB33370602 70		j3C9RCStQAJn3W5QKaUmPS	B	RAB33372905 RAB33370602
S	RAB33370601 70			S	RAB33372905 RAB33370601
....4	RAB33370701 80		tl0eJnUSr4xK9P(dohhoon.jeong)	B	RAB33372905 RAB33370701
....4	RAB33490201 90		iGis1lefrllyZm48C1P(dohhoon.jeong)	B	RAB33372905 RAB33490201
....4	RAB33371901 100		4rlGUUIC1ZUC35S0KaUmPS	B	RAB33372905 RAB33371901
....4	RAB33371401 110		NbJnPtl3SZ2qdc0C0KaUmPS	B	RAB33372905 RAB33371401
....4	RAB33372001 120		0QWLEipk0GX8V45QKaUmPS	B	RAB33372905 RAB33372001
....4	RAB35329802 130		jpXrLnBmfOON8V4KaUmPS	B	RAB33372905 RAB35329802
S	RAB35329801 130			S	RAB33372905 RAB35329801
....4	RAB33377701 140	1.0	u9gMWaaFT4oMwBE0KaUloW	B	RAB33372905 RAB33377701
....4	RAB33590401 150	1.0	h8Ea7MqLuhSpBr60KaUlos	B	RAB33372905 RAB33590401
....4	RAB37010601 160		vNgbxLgJx81Z8V0KaUmPS	B	RAB33372905 RAB37010601
....4	RAB33373104 170	1.0		B	RAB33372905 RAB33373104
.....5	RAB33416801 10	1.0	IN0FkrvXzp7Zy2i0KaUllv	B	RAB33373104 RAB33416801
.....5	RAB35949601 20		정도훈(dohhoon.jeong)	B	RAB33373104 RAB35949601
.....5	RAB33370901 30		Ole8shNqyLvob8Z0KaUmPS	B	RAB33373104 RAB33370901
.....5	RAB33371101 40		hsfaZJNYKcti850KaUmPS	B	RAB33373104 RAB33371101
.....5	RAB33416901 50	1.0	cgKRPg2W8bOJInk0KaUmOF	B	RAB33373104 RAB33416901
.....5	RAB33370601 60		if1ITu6RnYHUc8C0KaUmPS	B	RAB33373104 RAB33370601
.....5	RAB33370701 70		tl0eJnUSr4xK9P(dohhoon.jeong)	B	RAB33373104 RAB33370701
.....5	RAB33490201 80		iGis1lefrllyZm48C1P(dohhoon.jeong)	B	RAB33373104 RAB33490201

.....5	RAB33371901 90		4rlGUUIC1ZUC350240nhoon.jeong)	B	RAB33373104 RAB33371901
....4	MAF63587801180		정도훈(dohhoon.jeong)	B	RAB33372905 MAF63587801
S	RAB33372902 20			S	MDQ64176908 RAB33372902
..2	ADC30051601100	1.1	XPMEjZkHxxbJbs-6xrrsrP	B	ADC30055701ADC30051601
...3	MCR6840701210	1.1	0FE3ULcfhtFeTp_1Gamn8D	B	ADC30051601MCR68407012
....4	RSH31009914 10	1.0	vwsGh_55giOQ-fnQPjC7U0	B	MCR68407012RSH31009914
.....5	RSH31009915 10		vmAQ7tXhTiUM_R3jCB3Lf2	B	RSH31009914 RSH31009915
....4	RCL30084001 20			B	MCR68407012RCL30084001
...3	MKC6529962120	1.0	wsu7ihRWnaf4V0jZEe8sDC	B	ADC30051601MKC65299621
....4	AKF74134905 10		EmiPpCqX6s51tNntBY8R0P	B	MKC65299621AKF74134905
S	MKC6529961820			S	ADC30051601MKC65299618
...3	RAC32697304 30			B	ADC30051601RAC32697304
...3	1VZZA90001A40		2P4urTdnjTJRQ0HI85JKbY	B	ADC300516011VZZA90001A
...3	7250AL0033E 50		FoSKvgPU46nYUly0KaUmUX	B	ADC300516017250AL0033E
..2	AED75502401 110	1.0	PuHjTLvRVYf7Mpmmx7Liqp	B	ADC30055701AED75502401
...3	MEB6541430810		uoKkpaL5m9BhxXNJ4nEAdZ	B	AED75502401 MEB65414308
...3	MAZ6783360120		Thxe00phFvBFQTZ6JSCPe5	B	AED75502401 MAZ67833601
...3	MAZ6783360230		XKEHV-LKTg7rx5jhifUL5U	B	AED75502401 MAZ67833602
...3	1TCL0302818 40		pim9FX9JnPwpU5Sh451V56	B	AED75502401 1TCL0302818
..2	MJH64673101120	1.0	h-NBOQC7hOEAL8ee6IZ6Uu	B	ADC30055701MJH64673101
...3	RAA00720004 10			B	MJH64673101RAA00720004
..2	MCK71414904130		suu50qT1bN3_3Y3oCdb1qW	B	ADC30055701MCK71414904
..2	MEA63970507140	1.2	ryTttOAylE4-RPlfY6dcip	B	ADC30055701MEA63970507
...3	RAA33958201 10		yMKQsW5te8ZyOR0tjEpUmR	B	MEA63970507RAA33958201
...3	RCL30080501 20			B	MEA63970507RCL30080501
..2	MCK71457104150	1.0	eEJbAu3aFsyWbCzpVXb7iW	B	ADC30055701MCK71457104
...3	MCK7145710310	1.0	PIBj-XScW9oZ5wwZztOleO	B	MCK71457104MCK71457103
....4	RAA31737262 10		tZoFw0GK_TVDiBqlIGYk2bK	B	MCK71457103RAA31737262
....4	RCL30078501 20			B	MCK71457103RCL30078501
..2	MFT64808212160		hHfkewkklasz8f3xLs4sWG-	B	ADC30055701MFT64808212
..2	1WZZW3Z003B70		QEEmquGt-imKGMG7-iGIQR	B	ADC300557011WZZW3Z003B
Q	1WZZW3Z003B70		QEEmquGt-imKGMG7-iGIQR	Q	ADC300557011WZZW3Z003B
Q	1WZZW3Z003B70		QEEmquGt-imKGMG7-iGIQR	Q	ADC300557011WZZW3Z003B
Q	1WZZW3Z003B70		QEEmquGt-imKGMG7-iGIQR	Q	ADC300557011WZZW3Z003B
..2	1SZZW5N001C80		jelMb3kYXDo7rxgv0kp32I	B	ADC300557011SZZW5N001C
Q	1SZZW5N001C80		jelMb3kYXDo7rxgv0kp32I	Q	ADC300557011SZZW5N001C
Q	1SZZW5N001C80		jelMb3kYXDo7rxgv0kp32I	Q	ADC300557011SZZW5N001C
..2	1TTL0403118 190		qeZLvCTHwMW1IJ2Kn0zh9G	B	ADC300557011TTL0403118

..2	1SZZW5N001H200		px6h8KEIij151JC3FChonF	B	ADC300557011SZZW5N001H
Q	1SZZW5N001H200		px6h8KEIij151JC3FChonF	Q	ADC300557011SZZW5N001H
..2	1SBF0402418 210		BYes4OaKfPkf7xo0KaUm5Q	B	ADC300557011SBF0402418
Q	1SBF0402418 210		BYes4OaKfPkf7xo0KaUm5Q	Q	ADC300557011SBF0402418
Q	1SBF0402418 210		BYes4OaKfPkf7xo0KaUm5Q	Q	ADC300557011SBF0402418
..2	1TTL0402418 220		XhHe7pwalRF_3t-IVwAcYc	B	ADC300557011TTL0402418
Q	1TTL0402418 220		XhHe7pwalRF_3t-IVwAcYc	Q	ADC300557011TTL0402418
Q	1TTL0402418 220		XhHe7pwalRF_3t-IVwAcYc	Q	ADC300557011TTL0402418
..2	MAB62761315230		nVL0ipYuUJg93MixRd3i86	B	ADC30055701MAB62761315
..2	RAB33679005 240		Q6aOqw1v5LivAcKadJ(hoon.jeong)	B	ADC30055701RAB33679005
S	RAB33679003 240			S	ADC30055701RAB33679003
.1	MDX65456106410	1.0	oPpGVwgWco2GSHxO08fbRi	B	LSEL6335F.AR5VMDX65456106410KHQ
..2	MDX6545610510	1.1	iZpJK3tLuX6V2pXZEPlj0M	B	MDX65456106MDX65456105
...3	RAA32200045 10			B	MDX65456105RAA32200045
...3	RCL30081101 20		정도훈(dohoon.jeong)	B	MDX65456105RCL30081101
S	MDX65456104410			S	LSEL6335F.AR5VMDX65456104410KHQ
.1	ACQ88365230420	1.2	zT6UM310LK_IRQTOAWqMSJ	B	LSEL6335F.AR5VACQ88365230420KHQ
..2	MCK6847391110	1.3	Tanfj6uJMtvtvUPllzuq0d	B	ACQ88365230MCK68473911
...3	RAA33956555 10		JU3BYfdsVrWa0cbAwoCMJL	B	MCK68473911RAA33956555
...3	RCL30094501 20			B	MCK68473911RCL30094501
..2	MCK6682240320	1.2	eapLpCICAZL6FP60KaUmkQ	B	ACQ88365230MCK66822403
...3	RAA31629024 10			B	MCK66822403RAA31629024
...3	RCL30078801 20		정도훈(dohoon.jeong)	B	MCK66822403RCL30078801
..2	MCQ6708440730		Zq0mD9Q666uLWAB0kyaiHB(kim)	B	ACQ88365230MCQ67084407
..2	1TTL0402418 40		XhHe7pwalRF_3t-IVwAcYc	B	ACQ883652301TTL0402418
.1	MCK68473909430	1.2	UsBAnTJm0SMJD3DOSLXQ38	B	LSEL6335F.AR5VMCK68473909430KHQ
..2	RAA33956555 10		JU3BYfdsVrWa0cbAwoCMJL	B	MCK68473909RAA33956555
.1	MAG64132101440		0SYapkdqP2NRJp2M2eaN1g	B	LSEL6335F.AR5VMAG64132101440KHQ
S	MAG64123301440			S	LSEL6335F.AR5VMAG64123301440KHQ
.1	MFL69401915470		nV4FDSxGMmI_RAGRYJj2C4	B	LSEL6335F.AR5VMFL69401915470KHQ
.1	MFL68920532475		91YmvCdxis6USfDjhsdPmu	B	LSEL6335F.AR5VMFL68920532475KHQ
.1	MBM66437301180			B	LSEL6335F.AR5VMBM66437301180KHQ
.1	MBM67196403490		vib8nhvpECEadZJ6Rf5R_3	B	LSEL6335F.AR5VMBM67196403490KHQ
.1	MEZ66228802500	1.1	a5fkHDh1lhjMDCq0KaUIZb	B	LSEL6335F.AR5VMEZ66228802500KHQ
..2	3850W3B226A10		S3RbZwmQNHiiUfkO0KaUIMo	B	MEZ662288023850W3B226A
.1	MEZ65953055510	1.0		B	LSEL6335F.AR5VMEZ65953055510KHQ
..2	MEZ6873950110		dsdrKdEXsMgQjRjRj(hoon.jeong)	B	MEZ65953055MEZ68739501
.1	MEZ57156606520		HAI HUU NGUYEN(huu.hai.nguyen)	B	LSEL6335F.AR5VMEZ57156606520KHQ

.1	MEZ69101409530	1.2		B	LSEL6335F.ARS117A001V209KHQ
..2	MBM6491678110			B	MEZ69101409MBM64916781
..2	3850W3B226A20		S3RbZwmQNHuUfkO0KaUIMo	B	MEZ691014093850W3B226A
.1	FAD33778501 550		AEmwqRB6Pue7Rku0KaUmlC	B	LSEL6335F.ARS117A001V209KHQ
.1	1SZZW5N001A560		mLlfKlr5sDFUxokyEzptYz	B	LSEL6335F.ARS117A001V209KHQ
Q	1SZZW5N001A560		mLlfKlr5sDFUxokyEzptYz	Q	LSEL6335F.ARS117A001V209KHQ
Q	1SZZW5N001A560		mLlfKlr5sDFUxokyEzptYz	Q	LSEL6335F.ARS117A001V209KHQ
Q	1SZZW5N001A560		mLlfKlr5sDFUxokyEzptYz	Q	LSEL6335F.ARS117A001V209KHQ
.1	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	B	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTL0402418 570		XhHe7pwalRF_3t-IVwAcYc	Q	LSEL6335F.ARS117A001V209KHQ
.1	1SZZW2A004E580		RnAXuaknArBt_ywVaxncol	B	LSEL6335F.ARS117A001V209KHQ
Q	1SZZW2A004E580		RnAXuaknArBt_ywVaxncol	Q	LSEL6335F.ARS117A001V209KHQ
Q	1SZZW2A004E580		RnAXuaknArBt_ywVaxncol	Q	LSEL6335F.ARS117A001V209KHQ
.1	1TTG0402418 590		FmylXPDuAKuhf08z1BEd4P	B	LSEL6335F.ARS117A001V209KHQ
Q	1TTG0402418 590		FmylXPDuAKuhf08z1BEd4P	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTG0402418 590		FmylXPDuAKuhf08z1BEd4P	Q	LSEL6335F.ARS117A001V209KHQ
Q	1TTG0402418 590		FmylXPDuAKuhf08z1BEd4P	Q	LSEL6335F.ARS117A001V209KHQ
.1	1ATF0502610 600		xpGZAO6oN_Yln1eIRZR20C	B	LSEL6335F.ARS117A001V209KHQ
.1	4B70188C 610		RgfWgwgxcWfjQqe0KaUmH0	B	LSEL6335F.ARS117A001V209KHQ
Q	4B70188C 610		RgfWgwgxcWfjQqe0KaUmH0	Q	LSEL6335F.ARS117A001V209KHQ
Q	4B70188C 610		RgfWgwgxcWfjQqe0KaUmH0	Q	LSEL6335F.ARS117A001V209KHQ
.1	1TPL0402018 611		AE-9RVg64IG5_s5EqTuGgL	B	LSEL6335F.ARS117A001V209KHQ
.1	1TTL0402416 612		TAZNml3DLp_dHtPRwHuVc8	B	LSEL6335F.ARS117A001V209KHQ
.1	1SZZW5N001A515		qwR1eLpmmkTaCf1agxbdDU	B	LSEL6335F.ARS117A001V209KHQ
.1	1WZZW3Z003640		aOXEgnOFk4mbw0G0KaUlsV	B	LSEL6335F.ARS117A001V209KHQ
Q	1WZZW3Z003640		aOXEgnOFk4mbw0G0KaUlsV	Q	LSEL6335F.ARS117A001V209KHQ

Q	1WZZW3Z003640		aOXEgnOFk4mbw0G0KaUlsV	Q	LSEL6335F.ARS1WZZW3Z003640
Q	1WZZW3Z003640		aOXEgnOFk4mbw0G0KaUlsV	Q	LSEL6335F.ARS1WZZW3Z003640
.1	MAY66060610650			B	LSEL6335F.ARS1WZZW3Z003640
.1	MEZ66228946660	1.0		B	LSEL6335F.ARS1WZZW3Z003640
..2	MEZ6403481010		E0aidihaynSgxjk0KaUlpK	B	MEZ66228946MEZ64034810
.1	AGG74419317670	1.0	tRD5QAjn4d62o7BRcsH4Wb	B	LSEL6335F.ARS1WZZW3Z003640
..2	MFZ6748840110	1.0	g6pVnTjhH8hDKjuG3KP1bX	B	AGG74419317MFZ67488401
...3	RAA32339201 10			B	MFZ67488401RAA32339201
..2	MFZ6395300720		rUc72eh32Et6lfc0KaUmlP	B	AGG74419317MFZ63953007
..2	MAB6276131030		LhjWZCYncU0rATxD5lw9WU	B	AGG74419317MAB62761310
..2	MAB6276134540		4qnllwYQsW_RyxneoX7WDq	B	AGG74419317MAB62761345
..2	MAB6276134650		4qnllwYQsW_RyxneoX7WDq	B	AGG74419317MAB62761346
..2	MAB6276134060		4qnllwYQsW_RyxneoX7WDq	B	AGG74419317MAB62761340
.1	MFZ64771704672		elrATQHXSaXmAMz5qR34R7	B	LSEL6335F.ARS1WZZW3Z003640
.1	AGG00366003675	1.1	EPonC_KirEkM7cvX-JEjW4	B	LSEL6335F.ARS1WZZW3Z003640
..2	MCR6746850310	1.0	hpoOPmllWH6SNfc0KaUmMY	B	AGG00366003MCR67468503
...3	RCL30078201 10			B	MCR67468503RCL30078201
..2	AAA7590950820	1.4	3NGhqsAiWf9PvTDK94Le8w	B	AGG00366003AAA75909508
...3	MFZ6723950110	1.1	3LwWfZ1em5KNHHPG10nuvv	B	AAA75909508MFZ67239501
....4	RAA32339201 10			B	MFZ67239501RAA32339201
...3	MAB6276133420		4qnllwYQsW_RyxneoX7WDq	B	AAA75909508MAB62761334
...3	7250W5D000430		0wM4eHcwrIxCXgF5S04fk7	B	AAA759095087250W5D0004
..2	AAA3118971430	1.2	ECO	B	AGG00366003AAA31189714
...3	3880W1A015B10		78Q03YZQefCQYlb_jdQACq	B	AAA311897143880W1A015B
...3	3850W3B226A20		S3RbZwmQNHlUfkO0KaUlMo	B	AAA311897143850W3B226A
...3	MHL6341141340	1.0	1y75TBU52agCOE6DrAM2m7	B	AAA31189714MHL63411413
....4	RCL30086601 10			B	MHL63411413RCL30086601
....4	RCL30086101 20			B	MHL63411413RCL30086101
...3	MHL6489180950	1.1	92pONfDI4NdFEQq0KaUmbJ	B	AAA31189714MHL64891809
....4	RCL30083301 10			B	MHL64891809RCL30083301
....4	RCL30095401 20			B	MHL64891809RCL30095401
...3	MFL71878801 60		Qj8IHAGONrrkxd0aXghgBe	B	AAA31189714MFL71878801
...3	MBM662776120		84uSMKjqdMo9d6StD_WUZ9	B	AAA31189714MBM66277612
...3	MBM675116010		shDpf0hvH-v3AMC-rlwkp8	B	AAA31189714MBM67511601
...3	MBM654511140		5JEY3ivU6RUlNFx25Q-gch	B	AAA31189714MBM65451114
...3	AAA31192209100	1.3	P7x-5XkglrpPkz2M6tph8B	B	AAA31189714AAA31192209
....4	4Z50545C 10		5J8npF6tem4rTnPqAqF5WS	B	AAA311922094Z50545C
....4	4Z50545A 15		5J8npF6tem4rTnPqAqF5WS	B	AAA311922094Z50545A

....4	MBM375248020		fcyTNDloj-tpMz6KrQ-suc	B	AAA31192209MBM37524807
....4	AAA7497060230		WL3HdNcsNWuJ0i00KaUmT2	B	AAA31192209AAA74970602
....4	FAK30249601 40		owD2T6cw4kZ4mEX0bpFakJ	B	AAA31192209FAK30249601
....4	1SZZW1N003A50		8QNgeG5U4bv3tJ20KaUmlY	B	AAA311922091SZZW1N003A
....4	3850W3B226A60		S3RbZwmQNHlUfkO0KaUIMo	B	AAA311922093850W3B226A
....4	MAZ3487710370	1.2	Wh9LgcD1rU8t-Rmm8bCeI_	B	AAA31192209MAZ34877103
.....5	RCL30078501 10			B	MAZ34877103RCL30078501
...3	5001W5N001D110			B	AAA311897145001W5N001D
..2	3850W3B226A40		S3RbZwmQNHlUfkO0KaUIMo	B	AGG003660033850W3B226A
.1	MFZ67241901677	1.1	DLev0GGEZ6sHFFJjmQDeb1	B	LSEL6335F.ARS91636241901677MFZ67241901677BKHQ
..2	RAA32339201 10			B	MFZ67241901RAA32339201
.1	MAB63341603680		OkW1pkUepgM1Qrw0KaUmCL	B	LSEL6335F.ARS91636241901677MAB63341603680BKHQ
.1	MAB62761350690		4qnllwYQsW_RyxneoX7WDq	B	LSEL6335F.ARS916362761350690MAB62761350690BKHQ
.1	MAB62761329740		4qnllwYQsW_RyxneoX7WDq	B	LSEL6335F.ARS916362761329740MAB62761329740BKHQ
.1	RAB34971901 750		yaAeTKtxScKwTLu-5C5sZt	B	LSEL6335F.ARS916362761329740RAB34971901 750BKHQ
.1	MAF64527503760		pHWu5RHNbhoupLk0KaUmVD	B	LSEL6335F.ARS916362761329740MAF64527503760BKHQ
Q	MAF64527503760		pHWu5RHNbhoupLk0KaUmVD	Q	LSEL6335F.ARS916362761329740MAF64527503760BKHQ
.1	RAB34370005 780		eWc1w4YJ12x-8P5H09y0n9.yoon)	B	LSEL6335F.ARS916362761329740RAB34370005 780BKHQ
.1	RAB36916003 785		Lp_qeUXldMqE55Rg5jms4n)	B	LSEL6335F.ARS916362761329740RAB36916003 785BKHQ
Q	RAB36916003 785		Lp_qeUXldMqE55Rg5jms4n)	Q	LSEL6335F.ARS916362761329740RAB36916003 785BKHQ
Q	RAB36916003 785		Lp_qeUXldMqE55Rg5jms4n)	Q	LSEL6335F.ARS916362761329740RAB36916003 785BKHQ
.1	RAB36916002 790		Lp_qeUXldMqE55Rg5jms4n)	B	LSEL6335F.ARS916362761329740RAB36916002 790BKHQ
Q	RAB36916002 790		Lp_qeUXldMqE55Rg5jms4n)	Q	LSEL6335F.ARS916362761329740RAB36916002 790BKHQ
Q	RAB36916002 790		Lp_qeUXldMqE55Rg5jms4n)	Q	LSEL6335F.ARS916362761329740RAB36916002 790BKHQ
Q	RAB36916002 790		Lp_qeUXldMqE55Rg5jms4n)	Q	LSEL6335F.ARS916362761329740RAB36916002 790BKHQ
.1	RAB33679005 800		Q6aOqw1v5LivE0KadJhhoon.jeong)	B	LSEL6335F.ARS916362761329740RAB33679005 800BKHQ
Q	RAB33679005 800		Q6aOqw1v5LivE0KadJhhoon.jeong)	Q	LSEL6335F.ARS916362761329740RAB33679005 800BKHQ
Q	RAB33679005 800		Q6aOqw1v5LivE0KadJhhoon.jeong)	Q	LSEL6335F.ARS916362761329740RAB33679005 800BKHQ
S	RAB33679003 800			S	LSEL6335F.ARS916362761329740RAB33679003 800BKHQ
.1	3Z90435C 810	1.2	odoJmS6_YFf1Gj1LYVh1Tf	B	LSEL6335F.ARS9163627613297403Z90435C 810EKGH
..2	8PPP5B80001 10			B	3Z90435C 8PPP5B80001
.1	AGM7530904612	1.5	f9s907rch1QosWe73FFIBI	B	LSEL6335F.ARS916362761329740AGM7530904612BKHQ
..2	MJH6624680110	1.1		B	AGM7530904612MJH66246801
...3	RAA35359701 10		ANDREA CARDENAS(andreaCard...		MJH66246801RAA35359701
..2	AJX75331102 20	1.0	3YI2iByz3VwsEBU0KaUlwb	B	AGM7530904612AJX75331102
...3	MKC6545911810	1.0	GqlcnKgi04fWdU1EHol2s4	B	AJX75331102 MKC65459118
....4	AKF74335218 10			B	MKC65459118AKF74335218
...3	MFM644992020		1SHg6hBV_JGE9KP2_IPiWH	B	AJX75331102 MFM64499201

..2	7250PT0066N 30		S81kgTXo600OQp3eobHhZv	B	AGM753090467250PT0066N
.1	AGM75509809815	1.1	Bgte3veFo73GvyhjDC_pD9	B	LSEL6335F.ARS.AGM75509809815KHQ
..2	MFT6480821210		hHfkewkksz8f3xLs4sWG-	B	AGM75509809MFT64808212
..2	ADC3005160120	1.1	XPMEjZkHxxbJbs-6xrrsrP	B	AGM75509809ADC30051601
...3	MCR6840701210	1.1	0FE3ULcftFeTp_1Gamn8D	B	ADC30051601MCR68407012
....4	RSH31009914 10	1.0	vwsGh_55giOQ-fnQPjC7U0	B	MCR68407012RSH31009914
....5	RSH31009915 10		vmAQ7tXhTiUM_R3jCB3Lf2	B	RSH31009914 RSH31009915
....4	RCL30084001 20			B	MCR68407012RCL30084001
...3	MKC6529962120	1.0	wsu7ihRWnaf4V0jZEe8sDC	B	ADC30051601MKC65299621
....4	AKF74134905 10		EmiPpCqX6s51tNntBY8R0P	B	MKC65299621AKF74134905
S	MKC6529961820			S	ADC30051601MKC65299618
...3	RAC32697304 30			B	ADC30051601RAC32697304
...3	1VZZA90001A40		2P4urTdnjTJRQ0HI85JKbY	B	ADC300516011VZZA90001A
...3	7250AL0033E 50		FoSKvgPU46nYUly0KaUmUX	B	ADC300516017250AL0033E
.1	AKF75234401 820		QST581Prv_vQviCla_1rhd	B	LSEL6335F.ARS.AKF75234401KHQ
.1	MEZ68963201840		A2W5IKM5FDH5-Fvchphd7on jeong)	B	LSEL6335F.ARS.MEZ68963201KHQ
.1	MEZ69028403850		dDye-9hg5vPrMFmHGGu5Ri	B	LSEL6335F.ARS.MEZ69028403KHQ
.1	AGM30074603360	1.1	6mVeFDzGw4XTtgW0KaUmRM	B	LSEL6335F.ARS.AGM30074603KHQ
..2	MGC6637170810	1.1	SdjMfgEXmJ0wHiK0KaUmer	B	AGM30074603MGC66371708
...3	MGC6637170410	1.2	795k5e7YQ05e72e0KaUmdy	B	MGC66371708MGC66371704
....4	RSH31009910 10		lAqH4ifKgAfB8Nc0KaUmNa	B	MGC66371704RSH31009910
...3	AKF75718904 20		qwMpmeHokb0xsfc3xg5ln1	B	MGC66371708AKF75718904
...3	1VZZA90001A30		2P4urTdnjTJRQ0HI85JKbY	B	MGC663717081VZZA90001A
..2	MCQ6708442220		miQZ8XkZ0n5clUZKB_g5GA	B	AGM30074603MCQ67084422
.1	MEZ67714707870		DaHzee824-xwVh08xgZ4c7	B	LSEL6335F.ARS.MEZ67714707KHQ
.1	AGM30151201880	1.0	WcfhkhkyzMSQnfuhq66r9Yp	B	LSEL6335F.ARS.AGM30151201KHQ
..2	MFZ0050440110		Yij93q3FEKupJ9NT4VAqOE	B	AGM30151201MFZ00504401
..2	EAD63748816 20		XFOM1-hLVElGa4CNup0CTj	B	AGM30151201EAD63748816
..2	EBF62174906 30	1.0	w8pCGiRZYT9qej_hRvAQJ6	B	AGM30151201EBF62174906
...3	MHJ6587820110	1.0	eZUVV19ZoCPyf680KaUmV8	B	EBF62174906 MHJ65878201
...3	MCK7186640120	1.0	xmyoaH0xpsjKAXk0KaUloM	B	EBF62174906 MCK71866401
..2	EBF62174907 40	1.0	w8pCGiRZYT9qej_hRvAQJ6	B	AGM30151201EBF62174907
...3	MHJ6587820110	1.0	eZUVV19ZoCPyf680KaUmV8	B	EBF62174907 MHJ65878201
...3	MCK7186640120	1.0	xmyoaH0xpsjKAXk0KaUloM	B	EBF62174907 MCK71866401
..2	EBF62174908 50	1.0	w8pCGiRZYT9qej_hRvAQJ6	B	AGM30151201EBF62174908
...3	MHJ6587820110	1.0	eZUVV19ZoCPyf680KaUmV8	B	EBF62174908 MHJ65878201
...3	MCK7186640120	1.0	xmyoaH0xpsjKAXk0KaUloM	B	EBF62174908 MCK71866401