



H1
MountingHole
H2
MountingHole
H3
MountingHole
PWR_FLAG → VCC
PWR_FLAG → +3V3
PWR_FLAG → GND

X1
X2
X3
X4
X5
X6
X7
X8
X9
X10
X11
X12
X13
X14
X15
X16
X1
X2
X3
X4
X5
X6
X7
X8
X9
X10
J7
Conn_01x16_Socket
J8
Conn_01x10_Socket