




STEPPER
MOTOR
1B ●
2B ●
2A ●
1A ■

HEATER THROUGHPUT



TOOL 2

TEMP SENSE
THROUGHPUT



CUBE ZERO SWITCHER DISTRO BOARD

Rev 0

HEATER THROUGHPUT




TOOL 1

TEMP SENSE
THROUGHPUT



Partial pinout. Full documentation:
[github.com/
manufactory-dave/
CZSwitcher](https://github.com/manufactory-dave/CZSwitcher)

HEATER THROUGHPUT



TOOL 0

TEMP SENSE
THROUGHPUT

