



STEPPER  
MOTOR

1B  
2B  
2A  
1A

HEATER THROUGHPUT

24V

TOOL 2



CUBE ZERO  
SWITCHER DISTRO BOARD  
Rev 0

HEATER THROUGHPUT

24V

TOOL 1

Partial pinout. Full documentation:  
[github.com/manufactory-dave/CZSwitcher](https://github.com/manufactory-dave/CZSwitcher)

HEATER THROUGHPUT

24V

TOOL 0

BLTOUCH

PRB  
GND  
SERV  
5V  
GND

GND  
V+  
PRB  
DOCK CON  
SIG  
GND  
5V  
24V

3V3  
GND

5V  
GND

AUX 1  
GND  
SIG  
V+

DOCK CON  
SIG  
GND  
5V  
24V

AUX 0  
GND  
SIG  
V+

TEMP SENSE  
THROUGHPUT

GND  
SIG  
3V3