



1. CHARGING ON: CH "1"
 2. WAIT UNTIL THE CHARGE IS ACCUMULATED
 3. CHARGING OFF: CH "0"
 4. RELEASE CHARGE INTO THE FLIP-DISC: PL"1"
 5. WAIT 1ms
 6. TURN OFF THE CURRENT PULSE: PL"0"
- WWW.FLIPO.IO

FLIPO

FLIP-DISC PULSE SHAPER POWER SUPPLY

VIN: 12V; 1.5A

PL, CH - 3.3V-5V VOLTAGE LEVEL

PSPS-12V

V1

DATE: 12.01.2023