



Fixes:
 -01 & 02: FILTIN connects to 1.2V (won't work), you need to jumper 3.3V to FILTIN on CW312.
 -01 & 02: VREF missing on JTAG header, need to jumper if it using external JTAG programmer.