


49

J1
 1-2: FCC0
 3-4: FCD0
 5-6: FCE0
 7-8: FCF0

49

CN1 Electron Expansion Connector

CN Pass Through



1

