

Analog



Файл: analog.kicad_sch

Digital






Файл: digital.kicad_sch

IO & Power



Файл: io_and_power.kicad_sch



P.S. Unfortunately analog version of peak detector worked too poorly for low signal levels, so for now it is DNP (it is reimplemented in software)

Place jumper between 2-3

