


Make Sure These Caps are Close to VREG_IN and VREG_OUT



Sensors & Peripherals

File: Sensors & Peripherals.kicad_sch.kicad_sch

