




Running Light DIY Assembly Guide



1K Resistors (R1 to R10)



2.2K Resistor (R11)



10K Resistor (R12)

