



Shipping mark sticker



Broken stitch (M)

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.



Fabric hole at neck (M)

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

ITS Labtest Bangladesh Ltd., Haidar Tower, House # 668, Choydana, Ward # 34, Gazipur City Corporation, Gazipur-1704, Bangladesh

Tel: +88 0966 677 6669, Web: www.intertek.com

পূবালী ব্যাংক লিমিটেড
Pubali Bank Limited
Road Avenue শাখা

SND জমার ভাউচার

হিসাব নং 2706102001127 তারিখ 02/07/25
হিসাবের নাম Pubali Bank Limited
জমার বিবরণ (নগদ/চেক) ০২/০৭/২৫

ক্যাশ নং ২৩৬৫১৫
ব্যাচ/ক্রঃ নং
☐ অনলাইন

ক্যাশ নং ৭০০০০৭
জমা নং ০২/০৭/২৫

ক্যাশের নাম: Pubali Bank Limited
জমাদানকারীর নাম: Pubali Bank Limited

অফিসার

The results reflect our findings at time and place of inspection. This report does not relieve sellers/manufacturers from their contractual liabilities or prejudice buyers right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter This report does not evidence shipment.