





1. Table of Contents (This Page)  
Created on Sun Sep 8 23:37:40 2013


2. top
3. bottom
4. outline
5. plated-drill
6. unplated-drill
7. componentmask
8. soldermask
9. topsilk
10. bottomsilk
11. toppaste
12. topassembly
13. bottomassembly
14. fab


































There are 7 different drill sizes used in this layout, 286 holes total

Symbol	Diam. (Inch)	Count	Plated?
Y	0.013	199	YES
+	0.036	2	NO
x	0.039	2	NO
o	0.039	71	YES
□	0.051	2	YES
▽	0.068	4	YES
⊕	0.071	2	NO
⊗	0.126	4	NO

Title: pmc - Fabrication Drawing  
Author: Russ Dill  
Date: Mon 09 Sep 2013 06:37:40 AM GMT UTC



Board outline is the centerline of this path