




1. Table of Contents (This Page)


Created on Fri Sep 27 02:22:39 2013


- 2. top
- 3. bottom
- 4. outline
- 5. plated-drill
- 6. unplated-drill
- 7. componentmask
- 8. soldermask
- 9. topsilk
- 10. bottomsilk
- 11. toppaste
- 12. topassembly
- 13. bottomassembly
- 14. fab

































There are 7 different drill sizes used in this layout, 288 holes total

Symbol	Diam. (Inch)	Count	Plated?
Y	0.013	201	YES
+	0.036	2	NO
x	0.039	2	NO
o	0.039	71	YES
□	0.051	2	YES
▽	0.068	4	YES
⊕	0.071	2	NO
⊗	0.126	4	NO

Title: pmc - Fabrication Drawing
Author: Russ Dill
Date: Fri 27 Sep 2013 09:22:39 AM GMT UTC



Board outline is the centerline of this path