



This is the main diagram of the flange spindle holder - dimensions are in mm.





Flange drill holes for countersunk M5 hexagon socket head cap screw.

Refer to 3d file to see which side the holes
need to be countersunk from.



Countersunk screw head clearance showing depth of
each hole and diameter.



M3 pilot drill holes on top of shaft.

