



| SR no | Revision date | Version | Changes Description | Approved By | Designation | Prepared By | Designation |
|-------|---------------|---------|--|------------------|-------------|----------------------|------------------|
| 1 | 26-July-2018 | 2.1 | LAN designed using cisco L2/L3 switches | Mr. Somesh Auddy | CEO | Ishtiaq Nabi | Network Engineer |
| 2 | 6-May-2019 | 2.2 | Addition of L2 devices Cisco 300 Series | Mr. Somesh Auddy | CEO | Ishtiaq Nabi | Network Engineer |
| 3 | 8-Aug-2019 | 2.3 | Disconnection of ACT ILL | Mr. Somesh Auddy | CEO | Ishtiaq Nabi | Network Engineer |
| 4 | 15-Dec-2019 | 2.4 | Bandwidth ugradation Tikona- 30 to 35 MBPS | Mr. Somesh Auddy | CEO | Ishtiaq Nabi | Network Engineer |
| 5 | 24-Mar-2020 | 2.5 | Bandwidth Upgradation 75 MBPS | Mr. Pankaj Goyal | COO | Ishtiaq Nabi | Network Engineer |
| 6 | 1-April-2021 | 2.6 | MPLS Disconnection | Mr. Pankaj Goyal | COO | Ishtiaq Nabi | Network Engineer |
| 7 | 8-Mar-2022 | 2.7 | Reviewed (No changes Required) | Mr. Pankaj Goyal | COO | Bhabani Sankar Nayak | Network Engineer |
| 8 | 27-April-2022 | 2.8 | Reviewed Updated VLANs | Mr. Somesh Auddy | CEO | Bhabani Sankar Nayak | Network Engineer |