




\*\*\* NOTE \*\*\*

Rev 1 PCB is missing a 47k pull-up resistor from the \*RST pin (pin 6) to +3.3V.  
To make the board work, patch a 47k resistor onto the board underside.



PROGRAMMER  
INTERFACE (SWD)



GPIO CONNECTIONS

USB UART INTERFACE

## MSPM0L1105 Dev Board

Sheet: /  
File: MSPM0L1105\_dev\_board.kicad\_sch

**Title:**

Size: A4  
KiCad E.D.A. 9.0.1

Date:

**Rev:** 1  
Id: 1/1