













DrawCore



1. 5V power supply is provided by DC/DC. Output current is greater and less heat.
2. Add laser output interface, with PWM control ,connect to RB3
3. add 1x4P 2.54mm Away Headers for Stepper motor interface.
4. Potentiometer clockwise regulation is the current increases



Title: DrawCore	
Version:	
2016/8/30	
Drawn By: xiaoyu	1