



EDITS:

Cut trace between power switch and 5V line, making it only on/off.

FIXES NEEDED:

Audio amplifier doesn't boost enough for external speaker, even with higher gain resistors