

Security Markers Insertion

Linear Addressing Monitoring

Core

Instruction
Register

(II)

instructions

(I)

—we—

—reset—

—clk—

PC

PC+4

PC+imm

etc.

nextPC

(III)

—select_nextPC—

Security Markers Monitoring

Discontinuity Instructions Monitoring

