


Notes:

- 1) Add GND Looper
- 2) Add TP for JTAG
- 3) Change UART to UARTM (master)



thingSoC Reference Design Open Source Sockets for IoT		⊗ ⊗
TITLE: TSOC_GROVEY		⊗ ⊗
Document Number:	REV:	
Date: 8/15/2016 9:51:49 AM	Sheet: 1/1	

	1	2	3	4	5	6
A						
B						
C						
D						
E						



thingSoC

thingSoC Reference Design
Open Source Sockets for IoT



TITLE: TSOC_GROVEY

Document Number:

REV:

Date: 8/15/2016 9:51:49 AM

Sheet: 1/1



thingSoC Reference Design
Open Source Sockets for IoT

TITLE: TSOC_GROVEY

Document Number:

REV:

Date: 8/15/2016 9:51:49 AM

Sheet: 1/1

