




Notes:

- 1) Add GND Looper
- 2) Add TP for JTAG
- 3) Change UART to UARTM (master)



 thingSoC Reference Design		⊗ ⊗
Open Source Sockets for IoT		⊗ ⊗
TITLE: TSOC_GROVEY		
Document Number:		REV:
Date: 8/15/2016 9:51:49 AM		Sheet: 1/1

	1	2	3	4	5	6	
A							A
B							B
C							C
D							D
E							E

 thingSoC thingSoC Reference Design Open Source Sockets for IoT	
TITLE: TSOC_GROVEY	
Document Number:	REV:
Date: 8/15/2016 9:51:49 AM	Sheet: 1/1

