

To Set Up:  
 Connect 3 and 5  
 Plug in to PC  
 Open 9600 Baud  
 Serial Connection

Temp+  
 Humid.  
 Bcaster

To Run:  
 Connect  
 1&3  
 2&4

