

Instruction for Enhanced Filter Tools

11/29/2016

Check the firmware version:

Please make sure the firmware is greater than 1.09.3 and Serial Number greater than 16110100000 to perform the below task!

Check version:

1. Run CheckVersion.bat
2. Check the result from command.



```
C:\WINDOWS\system32\cmd.exe
c8b8080000#c3b5f022-5a42-1980-1909-ea72095601b1>
CPU: MX400U1
Hardware filter used
Y : 4
请按任意键继续. . .
```

Switch to Hardware Filter

1. Run SwitchToNormalFilter.bat
2. Unplug the camera and then plug it back in to the computer
3. Run Run_NiViewer_Without_Filter.bat
4. Check the depth stream

Switch to Software Filter

1. Run SwitchToEnhancedFilter.bat
2. Unplug the camera and then plug it back in to the computer
3. Run Run_NiViewer_With_Filter.bat
4. Check the depth stream