



TEKLİF FORMU

Sayın: Keten

Tarih: 06.11.2025

Belge No: KTNTS-05

A10-M15C21

Servis Takip No: SRV-0004

Stok Kodu / Stok Adı	Miktar	Liste Fiyatı	İnd. %	İnd. Fiyat	Toplam Fiyat
P01	1	₺50	20	₺40,00	40,00 ₺
P02	1	₺90	10	₺81,00	81,00 ₺
P05	1	₺8.000	90	₺800,00	800,00 ₺
ORİNG	4	₺60	100	₺0,00	0,00 ₺
Yağ değişimi	1,00	₺50,00	0,00	₺50,00	₺50,00
Havali Bakım	1,00	₺50,00	0,00	₺50,00	₺50,00
Servis kiti	1,00	₺30,00	0,00	₺30,00	₺30,00

Not: tamir masrafı çok yüksek 0 ürün önerilir



Ara Toplam: ₺1.051,00

Genel Toplam

₺1.051,00

* Fiyatlar KDV içermemektedir.

Saygılarımızla,
Keten Pnömatik

Fotoğraflar ve erişim linkleri:

/uploads/KTNTS-05/06dad241e7434259a824ffa53f552a5f.jpg (C:
Users\uur\OneDrive\Masaüstü\keten_work\erp\KetenErp.Api\bin\Debug\net8.0\wwwroot/uploads/
KTNTS-05/06dad241e7434259a824ffa53f552a5f.jpg)



TEKLİF FORMU

/uploads/KTNTS-05/eb27e55fb4e24f64a64fa9f2c2cdd004.png (C:
\\Users\\uur\\OneDrive\\Masaüstü\\keten_work\\erp\\KetenErp.Api\\bin\\Debug\\net8.0\\wwwroot/uploads/KTNTS-05/
eb27e55fb4e24f64a64fa9f2c2cdd004.png)

/uploads/KTNTS-05/7e002e3847a14cde8be4c3f605f3b320.jpg (C:
\\Users\\uur\\OneDrive\\Masaüstü\\keten_work\\erp\\KetenErp.Api\\bin\\Debug\\net8.0\\wwwroot/uploads/
KTNTS-05/7e002e3847a14cde8be4c3f605f3b320.jpg)