



TEKLİF FORMU

Sayın: Keten

Tarih: 06.11.2025

Belge No: KTNTS-05

A10-M15C21

Servis Takip No: SRV-0004

| Stok Kodu / Stok Adı | Miktar | Liste Fiyatı | İnd. % | İnd. Fiyat | Toplam Fiyat |
|----------------------|--------|--------------|--------|------------|--------------|
| P01 | 1 | ₺50 | 20 | ₺40,00 | 40,00 ₺ |
| P02 | 1 | ₺90 | 10 | ₺81,00 | 81,00 ₺ |
| P05 | 1 | ₺8.000 | 90 | ₺800,00 | 800,00 ₺ |
| ORİNG | 4 | ₺60 | 100 | ₺0,00 | 0,00 ₺ |
| Yağ değişimi | 1,00 | ₺50,00 | 0,00 | ₺50,00 | ₺50,00 |
| Havalı Bakım | 1,00 | ₺50,00 | 0,00 | ₺50,00 | ₺50,00 |
| Servis kiti | 1,00 | ₺30,00 | 0,00 | ₺30,00 | ₺30,00 |

Not: tamir masrafı çok yüksek 0 ürün önerilir



Ara Toplam: ₺1.051,00

Genel Toplam

₺1.051,00

* Fiyatlar KDV içermemektedir.

Saygılarımızla,
Keten Pnömatik

Fotoğraflar ve erişim linkleri:

/uploads/KTNTS-05/06dad241e7434259a824ffa53f552a5f.jpg (C:
\\Users\\uur\\OneDrive\\Masaüstü\\keten_work\\erp\\KetenErp.Api\\bin\\Debug\\net8.0\\wwwroot\\uploads/
KTNTS-05/06dad241e7434259a824ffa53f552a5f.jpg)



TEKLİF FORMU

/uploads/KTNTS-05/eb27e55fb4e24f64a64fa9f2c2cdd004.png (C:
\\Users\\uur\\OneDrive\\Masaüstü\\keten_work\\erp\\KetenErp.Api\\bin\\Debug\\net8.0\\wwwroot/uploads/KTNTS-05/
eb27e55fb4e24f64a64fa9f2c2cdd004.png)

/uploads/KTNTS-05/7e002e3847a14cde8be4c3f605f3b320.jpg (C:
\\Users\\uur\\OneDrive\\Masaüstü\\keten_work\\erp\\KetenErp.Api\\bin\\Debug\\net8.0\\wwwroot/uploads/
KTNTS-05/7e002e3847a14cde8be4c3f605f3b320.jpg)