












TITLE: Logic		REV: 0.7.3
	Company: Your Company	Sheet: 1/3
	Date: 2024-10-16	Drawn By: valzzu





ILI9341 cannot use display and touch on the same SPI.
The workaround is not connecting SDO / Miso.

TITLE: Displays		REV: 0.7.3
	Company: Your Company	Sheet: 3/3
	Date: 2024-10-27 Drawn By: valzzu	